



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 6920P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (NPA)	BUCKLED	-	-
10	FRONT BUMPER CLIPS (NPA)	NECESSARY	-	-
1	FRONT BUMPER CORNER RETAINER LH (NPA)	DISTORTED	-	-
1	FRONT BUMPER REINFORCEMENT (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT BUMPER SPONGE LH (NPA)	SERVICEABLE	-	-
1	FRONT BUMPER CORE SHUTTLE (NPA)	SERVICEABLE	-	-
1	FRONT BUMPER PARKING SENSOR LH (NPA)	SERVICEABLE	-	-
4	FRONT BUMPER PARKING SENSOR HOLDERS (NPA)	SERVICEABLE	-	-
1	FRONT BUMPER FOG LAMP LH (NPA)	SERVICEABLE	-	-
1	FRONT FENDER LH (NPA)	BENT	-	-
1	FRONT FENDER SHIELD (NPA)	CRACKED	-	-
10	FRONT FENDER SHIELD CLIPS (NPA)	NECESSARY	-	-
1	FRONT WHEEL RIM LH (NPA)	DENTED	-	-
1	FRONT SHOCK ABSORBER (NPA)	* CHECK	-	-
1	FRONT KNUCKLE ARM (NPA)	* CHECK	-	-
1	FRONT KNUCKLE ARM BEARING (NPA)	* CHECK	-	-
1	FRONT LOWER ARM (NPA)	* CHECK	-	-
1	FRONT LOWER ARM BALL JOINT LH (NPA)	* CHECK	-	-
1	FRONT LOWER ARM BRACKET LH (NPA)	SERVICEABLE	-	-
1	FRONT BEARING HUB (NPA)	* CHECK	-	-
1	FRONT STEERING RACK (NPA)	SERVICEABLE	-	-
1	FRONT STEERING TIE ROD LH (NPA)	SERVICEABLE	-	-
1	FRONT STEERING TIE ROD END LH (NPA)	SERVICEABLE	-	-
1	HEADLAMP LH (LED) (NPA)	SERVICEABLE	-	-
1	FRONT DOOR WING MIRROR LH (NPA)	CRACKED	-	-
1	FRONT DOOR WING MIRROR COVER LH (NPA)	* CHECK	-	-
1	FRONT DOOR WING MIRROR SIGNAL LAMP LH (NPA)	CUT	-	-
1	FRONT DOOR WING MIRROR GLASS LH (NPA)	CRACKED	-	-
1	FRONT DOOR GLASS LH (NPA)	CUT	-	-
1	FRONT DOOR GLASS OUTER MOULDING LH (NPA)	DENTED	-	-

Report Ref No. CS/AGI22002247/Kvy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 5% DISCOUNT		-	-
			-	-
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR GLASS SOLAR FILM (SN)	NECESSARY	180.00	60.00
			180.00	60.00
	<u>LABOUR</u>			
	TO CONDUCT ELECTRICAL CHECK, FOCUS HEADLAMP.		30.00	15.00
	TO APPLY RUST PROOFING / RESEAL TUFF COATING TREATMENT TO RESPRAY / REPLACED / REPAIR PANEL.		60.00	30.00
	TO DISMANTLE / REPLACE FRONT UNDER CARRIAGE TO FACILITATE REPAIR.	* CHECK	250.00	-
	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST.		80.00	60.00
	TO CONDUCT HIGH SPEED BALANCING.		80.00	20.00
	LABOUR CHARGE - PANEL BEATING, REPAIRING OF FRONT FENDER INNER PANEL, BONNET, FRONT N/S DOOR, REAR N/S DOOR & PART REPLACEMENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		700.00	500.00
	TO RESPRAY AFFECTED AREAS.		1,300.00	900.00
	TO RESEAL PAINT PROTECTION (DIAMOND RITE) TO SPRAY PAINT AREAS.	* CHECK	800.00	-
			3,300.00	1,525.00
	GRAND TOTAL		3,480.00	1,585.00
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,050.00 NETT)			1,585.00

Report Ref No. CS/AGI22002247/Kvy3e2

NOTE: LAST CONVERSATION WITH REPAIRER ON 16.5.23 STILL PENDING FOR PARTS PRICES

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.