

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG22002249/AQCE2**Date:** 03/10/2022**REFERENCE**

Insured/Claimant:	TAN YU PING SHARON	Policy No:	1900093882		
Date of Loss:	06/03/2022	Nature of Claim:	OD	Claim No:	5425276579SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SML487L</b>		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX052534
Reg. Date:	30/04/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF2K2053589
Colour:	White	Odometer:	35475 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$170,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	235/55R19	Rear Tyre Size:	235/55R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	33,437.00	8,384.80	25,052.20	74.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,672.00	2,122.00	6,550.00	75.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>42,109.00</b>	<b>10,506.80</b>	<b>31,602.20</b>	<b>75.05</b>
<b>- Excess (S\$)</b>	500.00	500.00	0.00	0.00
<b>(S\$)</b>	41,609.00	10,006.80	31,602.20	75.95
<b>+ GST 7.00/7.00% (S\$)</b>	2,912.63	700.48	2,212.15	75.95
<b>Nett Amount (S\$)</b>	<b>44,521.63</b>	<b>10,707.28</b>	<b>33,814.35</b>	<b>75.95</b>

**INSPECTION**

Date of Assignment:	10/03/2022		
Date Inspected:	09/03/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,080.00 FS	*2,504.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	338.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP-LH/RH	Not Necessary	84.00 FS	*- FS
4	2		*FRONT BUMPER CLOSING ELEMENT-LH/RH	Not Necessary	252.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	161.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	850.00 FS	*- FS
7	1		*FRONT BUMPER UNDERRUN BAR-SELENITE SILVER	Not Necessary	580.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	246.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	3,910.00 FS	*3,128.00 FS
10	1		*QUATTRO EMBLEM	Necessary	111.00 FS	*88.80 FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Cracked	271.00 FS	*216.80 FS
12	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Cut	1,302.00 FS	*1,041.60 FS
13	2		*FRONT BUMPER AIR GUIDE GRILLE END CAP-LH/RH	Not Necessary	206.00 FS	*- FS
14	4		*FRONT BUMPER LOCKING CLIP	Not Necessary	18.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	198.00 FS	*- FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,043.00 FS	*- FS
17	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	86.00 FS	*- FS
18	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
19	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
20	1		*A/C STICKER	Not Necessary	22.00 FS	*- FS
21	2		*HORN-LH/RH	Not Necessary	416.00 FS	*- FS
22	2		*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
23	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
24	2		*FRONT WHEEL HOUSING LINER-LH/RH	Not Necessary	606.00 FS	*- FS
25	2		*FRONT WHEEL SPOILER-LH/RH	Not Necessary	344.00 FS	*- FS
26	2		*FRONT WHEEL COVER-LH/RH	Necessary	1,418.00 FS	*1,134.40 FS
27	2		*HEADLIGHT MOUNTING-LH/RH	Cracked	264.00 FS	*210.40 FS
28	2		*LED HEADLIGHT-LH/RH	Not Necessary	17,416.00 FS	*- FS
29	2		*LIFT CYLINDER-LH/RH	Not Necessary	306.00 FS	*- FS
30	1		*LIFT CYLINDER HOSE	Not Necessary	145.00 FS	*- FS
31	2		*RADIATOR AIR GUIDE-LH/RH	Not Necessary	132.00 FS	*- FS
32	1		*RADIATOR AIR GUIDE-CENTER	Not Necessary	48.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE-UPPER	Not Necessary	55.00 FS	*- FS
34	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
35	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)**    **33,437.00**    **8,384.80**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,200.00	500.00
4	TO RESPRAY FRONT BUMPER,FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS	New	3,000.00	950.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,122.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >