

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002255/GVY3Q2**Date:** 30/05/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00127512100

Claimant Vehicle No : SMF8601C **Insured Vehicle No :** GBC1325S

Date of Loss: 22/02/2022 Nature of Claim: TP Claim No: SNM22D201367/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF8601C**

Make & Model: SKODA OCTAVIA, 2.0 RS TSI AIDISPLAY (A) Engine No: DLB028769

Reg. Date: 27/11/2018 (Man. Year: 2018) Chassis No: TMBBU7NE8K0036189

Colour: White Odometer: 73022 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35Z R19 Rear Tyre Size: 235/35Z R19

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,355.00	1,726.50	4,628.50	72.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,170.00	610.00	3,560.00	85.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	10,525.00	2,336.50	8,188.50	77.80
+ GST 7.00/7.00% (\$\$)	736.75	163.56	573.19	77.80
Nett Amount (\$\$)	11,261.75	2,500.06	8,761.69	77.80

INSPECTION

Date of Assignment: 09/03/2022

Date Inspected: 16/03/2022 Inspected At:

Estimated Period of Repair: 3.0 days

Xin Yun Auto Pte Ltd (HQ)
BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER
@KAKI BUKIT
Singapore 415675

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 May 2022)

Parts: 143 SKODA OCTAVIA 2.0 RS TSI AIDISPLAY (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMF8601C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER LEFT SIDE RETAINER	Not Necessary	180.00 F	*- FL
2	1		*FOG LAMP LH EYEBROW CHROME	Not Necessary	150.00 F	*- FL
3	1		*FOG LAMP CHROME BASE COVER	Not Necessary	220.00 F	*- FL
4	1		*FOG LAMP	Not Necessary	250.00 F	*- FL
5	1		*FRONT LEFT FENDER	Dented	985.00 F	*985.00 FL
6	1		*FRONT LEFT FENDER INNER COWLING	Not Necessary	245.00 F	*- FL
7	1		*FRONT LEFT FENDER INNER GARNISH	Not Necessary	80.00 F	*- FL
8	1		*SET FRONT LEFT SUSPENSION ASSY FULL	Not Necessary	980.00 F	*- FL
9	1		*FRONT LEFT CONTROL ARM	Not Necessary	780.00 F	*- FL
10	2		*FRONT TIE ROD END AND LINK	Not Necessary	485.00 F	*- FL
11	1		*FRONT RIGHT WHEEL HUB WITH BEARING	Not Necessary	380.00 F	*- FL
12	1		*SPORT RIM	Cut	900.00 F	*900.00 FL
13	1		*SPORT RIM CAP	Not Necessary	100.00 F	*- FL
14	1		*TYRE	Not Necessary	300.00 F	*- FL
15	10		*FRONT BUMPER CLIPS	Not Necessary	60.00 FS	*- FS
16	6		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
17	8		*FRONT BUMPER SIDE TRIM CLIPS	Not Necessary	50.00 FS	*- FS
18	6		*FRONT FENDER INNER COWLING CLIPS	Necessary	30.00 FS	*30.00 FS
19	8		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
20	1		*NUMBER PLATE AND CASING	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,355.00	1,915.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	188.50
Total Parts (\$\$)	6,355.00	1,726.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS	New	1,200.00	250.00
2	TO PUTTY AND SPRAY PAINTING FRONT PORTION	New	1,500.00	250.00
3	TO APPLY ANTI RUST PROOFING TO FRONT LEFT AFFECTED AREA	New	120.00	60.00
4	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	60.00	0.00
5	TO REMOVE AND INSTALL FRONT LEFT UNDERCARRIAGE PARTS	New	350.00	0.00
6	TO CHECK ,REMOVE AND REPLACE AIRCON RELATED RADIATOR ,CONDENSOR ETC CHECK AIRCON ,TOP UP GAS ETC	New	200.00	0.00
7	TO BALANCE FRONT WHEEL	New	120.00	0.00
8	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
9	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM ASSY	New	100.00	0.00
10	TO DO REPROGRAMMING TO REMOVE FAULT CODE	New	200.00	0.00
11	REMOVE BODY STICKER AND REPLACE NEW STICKER	New	200.00	50.00
Gross Labour Cost (S\$)			4,170.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >