

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002256/KTY3N2**Date:** 17/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00247012100

Claimant Vehicle No : SKZ8072Y **Insured Vehicle No :** SMT7672E

Date of Loss: 15/02/2022 Nature of Claim: TP Claim No: SNM22D201177/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ8072Y**

Make & Model: TOYOTA WISH, 1.8 X CVT (A) Engine No: 2ZR1634573

Reg. Date: 04/02/2016 (Man. Year: 2015) Chassis No: ZGE206026405

Colour: Metallic Pearl White Odometer: 131450 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15

Front Left Side: Tourador 2 mm Rear Left Side: Tourador 3 mm

Front Right Side: Tourador 2 mm Rear Right Side: Tourador 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,102.50	2,202.77	1,899.73	46.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	1,570.00	2,230.00	58.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,902.50	3,772.77	4,129.73	52.26
Approved Total (Overridden) (\$\$)		3,000.00		
(\$\$)	7,902.50	3,000.00	4,902.50	62.04
+ GST 7.00/7.00% (\$\$)	553.18	210.00	343.18	62.04
Nett Amount (\$\$)	8,455.68	3,210.00	5,245.68	62.04

INSPECTION

Date of Assignment: 09/03/2022

Date Inspected: 10/03/2022 Inspected At: Cartimes Autolution Pte Ltd
160 Sin Ming Drive #02-04 Autocity,
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ8072Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,400.00 FL	*1,272.00 FL
2	1		*TAILGATE INNER TRIM	Serviceable	500.00 FL	*- FL
3	1		*TAILGATE LOCK ASSY	Repair	450.00 FL	*- FL
4	1		*TAILGATE CENTRE GARNISH	Serviceable	200.00 FL	*- FL
5	1		*TAILGATE LAMP LHS	Serviceable	300.00 FL	*- FL
6	1		*TAILGATE LAMP RHS	Serviceable	300.00 FL	*- FL
7	1		*TOYOTA EMBLEM	Necessary	80.00 FL	*80.00 FL
8	1		*VALVE EMBLEM	Necessary	80.00 FL	*80.00 FL
9	1		*REAR BUMPER	Buckled	600.00 FL	*566.10 FL
10	1		*END PANEL	Bent	540.00 FL	*540.00 FL
11	1		*END PANEL TOP GARNISH	Mtg Distorted	300.00 FL	*265.60 FL
12	1		*TAILGATE WEATHERSTRIP	Serviceable	320.00 FL	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
14	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
15	1		*REAR SENSORS	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,370.00	2,903.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,267.50	700.93
Total Parts (\$\$)	4,102.50	2,202.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS AND COMPONENTS	New	1,600.00	600.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,600.00	660.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	100.00	20.00
4	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	100.00	60.00
5	TRANSFER TAILGATE PARTS	New	150.00	60.00
6	REMOVE & REFIT REAR WINDSCREEN	New	150.00	120.00
7	REMOVE & REFIT REAR SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			3,800.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >