

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22002259/UQY3E2

Date: 27/05/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00003712200
Claimant Vehicle No: SFB325G Insured Vehicle No: SMQ8124E
Date of Loss: 08/03/2022 Nature of Claim: TP Claim No: SNM22D201653/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFB325G
Make & Model: RENAULT FLUENCE, 1.5 D DCI 110 (A) Engine No: K9KN837R000216
Reg. Date: 23/05/2017 (Man. Year: 2015) Chassis No: VF1LZLF0E54491634
Colour: White Odometer: 214752 km
Engine Capacity: 1461 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: KAPSEN 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: KAPSEN 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,161.76	14,407.76	7,754.00	34.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,940.00	3,120.00	820.00	20.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	26,101.76	17,527.76	8,574.00	32.85
Approved Total (Overridden) (\$\$)		14,000.00		
Nett Amount (\$\$)	26,101.76	14,000.00	12,101.76	46.36

INSPECTION

Date of Assignment: 26/04/2022
Date Inspected: 10/03/2022 Inspected At: 159 Tick Hai Motor (HQ)
#01-54 Autobay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2022)
Parts:	143	RENAULT FLUENCE 1.5 D DCI 110 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFB325G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET LOCK	Not Necessary	133.38 FL	*- FL
2	1		*FRONT BUMPER	Dented / Torn	1,259.93 FL	*1,259.93 FL
3	1		*FRONT BUMPER LOWER GRILLE	Torn	393.23 FL	*393.23 FL
4	1		*FRONT BUMPER SIDE RETAINER X 2 PCS	Not Necessary	160.50 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	609.90 FL	*609.90 FL
6	1		*FRONT BUMPER UNDERCOVER	Torn	256.60 FL	*256.60 FL
7	1		*FRONT BUMPER CLIP X 1 SET	Necessary	30.00 FL	*30.00 FL
8	1		*FRONT TOWING COVER	Not Necessary	48.50 FL	*- FL
9	1		*FOGLAMP COWLING X 2 PCS	Not Necessary	173.34 FL	*- FL
10	1		*FOGLAMP COVER X 2 PCS	Not Necessary	706.20 FL	*- FL
11	1		*FOGLAMP X 2 PCS	Not Necessary	465.45 FL	*- FL
12	1		*FRONT GRILLE	Cracked	365.94 FL	*365.94 FL
13	1		*FRONT LOGO	Not Necessary	208.65 FL	*- FL
14	1		*HEADLAMP LOWER RETAINER X 2 PCS	Not Necessary	170.00 FL	*- FL
15	1		*HEADLAMP X 2 PCS	Cracked	1,851.20 FL	*1,851.20 FL
16	1		*AIR CON CONDENSER	Bent / Punctured	812.00 FL	*802.50 FL
17	1		*INTERCOOLER	Punctured / Dented	834.15 FL	*834.15 FL
18	1		*HORN	Serviceable	85.60 FL	*- FL
19	1		*RADIATOR COWLING X 2 PCS	Not Necessary	108.20 FL	*- FL
20	1		*RADIATOR	Serviceable	1,213.00 FL	*- FL
21	1		*FRONT FENDER (LH)	Repair	543.90 FL	*- FL
22	1		*REAR BOOT	Dented	1,848.00 FL	*1,815.00 FL
23	1		*REAR BOOT RENAULT LOGO	Necessary	170.50 FL	*170.50 FL
24	1		*REAR BOOT UNDERCOVER	Torn	286.40 FL	*286.40 FL
25	1		*REAR BOOT UNDERCOVER CLIP X 1 SET	Necessary	30.00 FL	*30.00 FL
26	1		*REAR BOOT WEATHERSTRIP	Twisted	225.50 FL	*225.50 FL
27	1		*REAR NUMBER PLATE TOP GARNISH	Not Necessary	331.91 FL	*- FL
28	1		*REAR NUMBER PLATE LAMP X 2 PCS	Not Necessary	209.00 FL	*- FL
29	1		*REAR BOOT LAMP 1 PC	O/s Cracked	1,156.80 FL	*505.00 FL
30	1		*REAR BOOT LOCK	Jammed	308.00 FL	*308.00 FL
31	1		*REAR BOOT LOCK CATCH	Not Necessary	46.20 FL	*- FL
32	1		*REAR BOOT LOCK CATCH GARNISH	Not Necessary	68.90 FL	*- FL
33	1		*TAILLAMP X 2 PCS	Cracked	1,109.38 FL	*1,109.38 FL
34	1		*TAILLAMP LOWER RETAINER X 2 PCS	Cracked	52.80 FL	*52.80 FL
35	1		*REAR BUMPER	Distorted	920.70 FL	*920.70 FL
36	1		*REAR BUMPER CLIP X 1 SET	Necessary	30.00 FL	*30.00 FL
37	1		*REAR BUMPER SIDE RETAINER X 2 PCS	Bent	96.80 FL	*96.80 FL
38	1		*REAR BUMPER CENTRE RETAINER	Distorted	314.00 FL	*314.00 FL
39	1		*REAR BUMPER REINFORCEMENT	Distorted	603.90 FL	*603.90 FL
40	1		*REAR FENDER X 2 PCS	Repair	2,757.80 FL	*- FL
41	1		*END PANEL	Badly Dented	973.06 FL	*973.06 FL
42	1		*END PANEL TOP GARNISH	Twisted	618.20 FL	*618.20 FL
43	1		*AIR DUCT (RH)	Not Necessary	68.50 FL	*- FL
44	1		*SPARE TYRE COMPARTMENT PANEL	Crumpled	570.24 FL	*570.24 FL
45	1		*SPARE TYRE COMPARTMENT TOP BOARD	Warped	365.91 FL	*365.91 FL
46	1		*SPARE TYRE TOOL SPONGE BOX	Torn	142.56 FL	*142.56 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR EXHAUST HEAT SHIELD	Distorted	145.00 FL	*145.00 FL
48	1		*FRONT NUMBER PLATE WITH CASING	Bent	60.00 FS	*40.00 FS
49	1		*REVERSE SENSOR X 2 PCS	Shorted	350.00 FS	*200.00 FS
50	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
51	1		*WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
52	1		*END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
53	1		*REAR FENDER SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	24,549.73	15,976.40
- List Item Discount on L Items 10.00/10.00% (\$)	2,387.97	1,568.64
Total Parts (\$)	22,161.76	14,407.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT & REAR ELECTRICAL WIRING SYSTEM AND FOCUS HEADLAMPS	New	180.00	30.00
2	TO REMOVE & REINSTALL A/C CONDENSER, RADIATOR & INTERCOOLER, AND REFILL A/C GAS	New	250.00	100.00
3	TO REMOVE & INSTALL REVERSE SENSORS	New	80.00	50.00
4	TO TRANSFER REAR BOOT COMPONENTS FROM OLD BOOT TO NEW BOOT	New	150.00	60.00
5	TO REMOVE & INSTALL REAR WINDSCREEN TO FACILITATE REPAIR	New	150.00	0.00
6	TO REMOVE & INSTALL INTERIOR TRIMS & GARNISHES ETC TO FACILITATE REPAIR	New	180.00	80.00
7	TO APPLY ANTI-RUSTING COATING ON OLD AND NEW PANELS	New	250.00	100.00
8	LABOUR TO REMOVE, CUT, CHANGE & PANEL BEATING	New	1,500.00	1,500.00
9	TO PUTTY AND RESPRAY AFFECTED AREAS	New	1,200.00	1,200.00
Gross Labour Cost (\$)			3,940.00	3,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >