

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Stve Pte Ltd c/o No. 1 Kaki Bukit Ave 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883		Date : 03/06/2016 Reference No : CAS/16-06/011	
<u>General Information</u>			
Registration No. : GBC 4920D Accident Date : 10/05/2016			
<u>Particulars of Damaged Vehicle</u>			
Colour : Yellow	Make & Model : Toyota Hiace Manual		
Engine Capacity : 2982 cc	Pre-Accident Condition : Good		
Mileage (KM) : 175396	Engine No. : 1KD2168593		
Chassis No. : JTFHT02PX00089524	Steering : In Order		
Registration Date : 28/09/2012	Brake : In Order		
<u>Tyre Condition</u>			
	Size	Make	Balance
R/H Front Tyre	195R15	TRIANGLE	60%
L/H Front Tyre	195R15	TRIANGLE	60%
R/H Rear Tyre	195R15	TRIANGLE	60%
L/H Rear Tyre	195R15	TRIANGLE	60%
<u>Inspection</u>			
Repairer : Liu's Brother Auto Engineering Workshop No. 1 Kaki Bukit Ave 6, #01-01 Auto Bay @ Kaki Bukit, Singapore 417883			
<u>Adjustment And Recommendation Cost Of Repair</u>			
Repairer's Estimate : \$6,455.34			
Revised Amount : \$4,250.00			
Less Excess : -			
Nett Total : \$4,250.00			
<u>Remarks</u>			
(A) Survey was done on 26/05/2016 (B) Re-survey was done on 31/05/2016 (C) The survey was conducted entirely on WITHOUT PREJUDICE basis. (D) We have NOT given any instruction to authorize the repair of the vehicle.			

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Submit HS \$3800 HYS

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - LIST ITEMS</u>					
1	1pc	Front bumper <i>cut/de</i>	Cut/Deformed	796.80	796.80 ✓
2	1pc	Front bumper side holder LH <i>11</i>	Broken	68.50	68.50 X
3	1pc	Front head lamp LH <i>scr</i>	Scratched/Cut	725.70	725.70 ✓
4	1pc	Front step garnish LH <i>de</i>	Dented/Deformed	245.90	245.90 ✓
5	1pc	Front door LH <i>DD</i>	Dented	1,568.80	1,568.80 ✓
6	1pc	Front door weatherstrip LH <i>nu</i>	Necessary	108.60	108.60 ✓
7	1pc	Front door inner lock LH <i>nu</i>	Serviceable	374.50	- X
8	1pc	Front door view mirror assy LH <i>520</i>	Broken	845.10	845.10 ✓
9	1pc	Front door glass outer moulding LH <i>cut</i>	Cut	172.45	172.45 ✓
10	2pcs	Front door hinge LH @ \$98.50 <i>11</i>	Bent	197.00	197.00 X
11	1pc	Front door inner trim board LH <i>11</i>	Serviceable	645.10	- X
				5,748.45	4,728.85
Less 25%				(1,437.11)	(1,182.21)
Sub total				4,311.34	3,546.64
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>					
1	1set	Front bumper clip <i>nu</i>	Necessary	48.00	48.00 40
2	1pc	Front head lamp clip LH <i>nu</i>	Necessary	6.50	6.50 ✓
3	3pcs	Front step garnish clip @ \$6.50 <i>nu</i>	Necessary	19.50	19.50 ✓
4	1pc	Front door 'ROC' sticker LH <i>nu</i>	Necessary	50.00	50.00 30
5	1pc	Front door corporate sticker LH <i>nu</i>	Necessary	380.00	380.00 300
6	1pc	Front door sealant LH <i>nu</i>	Necessary	50.00	50.00 ✓
Sub total				4,865.34	4,100.64
<u>LABOUR & MISC. CHARGES</u>					
1		To check all wiring & electrical component for proper function		50.00	40.00 20
2		To remove, replace & transfer door panel, fitting & mechanisms		100.00	70.00 60
3		To apply rust proofing, reseal tuff-coating treatment on accident area		80.00	60.00 40
4		Labour for panel beating, cut, weld, straighten & replacing parts etc		680.00	550.00 380
5		To putty & spray painting & including touch up paint on accident affected areas		680.00	500.00 450
Grand total				6,455.34	5,320.64
Recommended cost of lump sum repair (To its pre-accident condition)					4,250.00

7-4463-38

252

P-3347-51

S.N. 446-00

L- 950

4743-57

3794

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$4,250.00 on a contractual basis. Under normal circumstances, the repair period would be about 4 (Four) working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)

MSAAA