

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant\_as@yahoo.com.sg

RCB No. 53138015K

## INVOICE

To: Stve Pte Ltd  
c/o No. 1 Kaki Bukit Ave 6  
#01-01 Auto Bay @ Kaki Bukit  
Singapore 417883

Date : 03/06/2016

Invoice No : IV16-06011/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of:  Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle GBC 4920D (Inclusive Of Photographs And Transport Charges)  Our reference : CAS/16-06/011	\$410.00
Total	\$410.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant\_as@yahoo.com.sg

RCB No. 53138015K

## Automobile Inspection Report

To: Stve Pte Ltd  
c/o No. 1 Kaki Bukit Ave 6  
#01-01 Auto Bay @ Kaki Bukit  
Singapore 417883

Date : 03/06/2016

Reference No : CAS/16-06/011

### General Information

Registration No. : GBC 4920D  
Accident Date : 10/05/2016

### Particulars of Damaged Vehicle

Colour	: Yellow	Make & Model	: Toyota Hiace Manual
Engine Capacity	: 2982 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 175396	Engine No.	: 1KD2168593
Chassis No.	: JTFHT02PX00089524	Steering	: In Order
Registration Date	: 28/09/2012	Brake	: In Order

### Tyre Condition

	Size	Make	Balance
R/H Front Tyre	195R15	TRIANGLE	60%
L/H Front Tyre	195R15	TRIANGLE	60%
R/H Rear Tyre	195R15	TRIANGLE	60%
L/H Rear Tyre	195R15	TRIANGLE	60%

### Inspection

Repairer : Liu's Brother Auto Engineering Workshop  
No. 1 Kaki Bukit Ave 6, #01-01 Auto Bay @ Kaki Bukit, Singapore 417883

### Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$6,455.34  
Revised Amount : \$4,250.00  
Less Excess : -  
Nett Total : \$4,250.00

### Remarks

- (A) Survey was done on 26/05/2016
- (B) Re-survey was done on 31/05/2016
- (C) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (D) We have NOT given any instruction to authorize the repair of the vehicle.

**NOTE:** The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.



**Adjustment On Repair Costs And Replacement Of Parts:**

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<b><u>PARTS REPLACEMENT – LIST ITEMS</u></b>					
1	1pc	Front bumper	Cut/Deformed	796.80	796.80
2	1pc	Front bumper side holder LH	Broken	68.50	68.50
3	1pc	Front head lamp LH	Scratched/Cut	725.70	725.70
4	1pc	Front step garnish LH	Dented/Deformed	245.90	245.90
5	1pc	Front door LH	Dented	1,568.80	1,568.80
6	1pc	Front door weatherstrip LH	Necessary	108.60	108.60
7	1pc	Front door inner lock LH	Serviceable	374.50	-
8	1pc	Front door view mirror assy LH	Broken	845.10	845.10
9	1pc	Front door glass outer moulding LH	Cut	172.45	172.45
10	2pcs	Front door hinge LH @ \$98.50	Bent	197.00	197.00
11	1pc	Front door inner trim board LH	Serviceable	645.10	-
Less 25%				5,748.45 (1,437.11)	4,728.85 (1,182.21)
Sub total				4,311.34	3,546.64
<b><u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u></b>					
1	1set	Front bumper clip	Necessary	48.00	48.00
2	1pc	Front head lamp clip LH	Necessary	6.50	6.50
3	3pcs	Front step garnish clip @ \$6.50	Necessary	19.50	19.50
4	1pc	Front door 'ROC' sticker LH	Necessary	50.00	50.00
5	1pc	Front door corporate sticker LH	Necessary	380.00	380.00
6	1pc	Front door sealant LH	Necessary	50.00	50.00
Sub total				4,865.34	4,100.64
<b><u>LABOUR &amp; MISC. CHARGES</u></b>					
1		To check all wiring & electrical component for proper function		50.00	40.00
2		To remove, replace & transfer door panel, fitting & mechanisms		100.00	70.00
3		To apply rust proofing, reseal tuff-coating treatment on accident area		80.00	60.00
4		Labour for panel beating, cut, weld, straighten & replacing parts etc		680.00	550.00
5		To putty & spray painting & including touch up paint on accident affected areas		680.00	500.00
Grand total				6,455.34	5,320.64
Recommended cost of lump sum repair (To its pre-accident condition)					4,250.00

**Constant Appraiser Services**

Vehicle No : GBC 4920D

Our ref : CAS/16-06/011

**Adjustment/Recommendations**

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$4,250.00** on a contractual basis. Under normal circumstances, the repair period would be about **4 (Four)** working days.

Yours faithfully,

**Constant Appraiser Services**



Lim Yong Tian (Sebastian)  
Licensed Appraiser  
Adv. Dip. In Mechanical Engineering (AUS)  
MSAAA











































