



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 1066K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	EXHAUST COVER (MIDDLE)	ABRADED	120.00	120.00
1	WINKER FRONT RIGHT	BROKEN	60.00	60.00
1	BRAKE LEVER	ABRADED	38.00	38.00
1	FRONT COVER, RIGHT	CRACKED	180.00	180.00
	LESS 10% DISCOUNT		-39.80	-39.80
			358.20	358.20
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	CARBON FIBRE LEG SHIELD (SN)	ABRADED	450.00	200.00
1	CARBON FIBRE U-COVER TOP (SN)	ABRADED	180.00	100.00
1	CARBON FIBRE EXHAUST COVER (SN)	ABRADED	150.00	100.00
1	CARBON FIBRE EXHAUST TIP (SN)	ABRADED	70.00	50.00
1	BCD MIRROR F1 PRO SERIES (SN)	ABRADED	120.00	80.00
1	CARBON FIBRE AIR FILTER COVER (SN)	SCRAPED	200.00	150.00
			1,170.00	680.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		40.00	20.00
	SPRAY PAINTING - TRANSMISSION COVER & NECESSARY AREAS.		200.00	100.00
	LABOUR CHARGES REMOVE AND REPLACE DAMAGED PARTS AND TO ALIGN FRONT FORKS.		480.00	300.00
			720.00	420.00
	<b>GRAND TOTAL</b>		<b>2,248.20</b>	<b>1,458.20</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>1,458.20</b>

Report Ref No. CS3/GRB21011113/Rqy3s2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.