

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002267/ETY3Q2**Date:** 30/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00052642108

Claimant Vehicle No : GBH6962T **Insured Vehicle No :** GBC6625T

Date of Loss: 08/03/2022 Nature of Claim: TP Claim No: SNM22D201673/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH6962T**

Make & Model: NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M) Engine No: YD25426087A

Reg. Date: 31/08/2018 (Man. Year: 2017) Chassis No: JN1MC2E26Z0009051

Colour: Red Odometer: 64003 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,780.75	14,059.82	16,720.93	54.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,230.00	4,060.00	2,170.00	34.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,010.75	18,119.82	18,890.93	51.04
Approved Total (Overridden) (S\$)		14,500.00		
(S\$)	37,010.75	14,500.00	22,510.75	60.82
+ GST 7.00/7.00% (S\$)	2,590.75	1,015.00	1,575.75	60.82
Nett Amount (S\$)	39,601.50	15,515.00	24,086.50	60.82

INSPECTION

Date of Assignment: 10/03/2022

Date Inspected: 11/03/2022 Inspected At: Efficient Motor & Engineering Works Pte Ltd (HQ)
56 Loyang Way #06-07, Loyang Enterprise Building
Singapore 508775

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 30 May 2022)	
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5MT 5DR (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH6962T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	571.90 FL	*571.90 FL
2	2		*FRONT BUMPER SIDE RETAINER LH/RH	Broken	362.00 FL	*362.00 FL
3	1		*FRONT BUMPER CENTER GRILLE	Not Necessary	912.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Dented	705.00 FL	*528.00 FL
5	1		*FRONT GRILLE	Missing	940.00 FL	*479.30 FL
6	1		*FRONT GRILLE LOGO	Missing	120.70 FL	*80.00 FL
7	2		*HEADLAMP LH/RH	Broken	1,248.00 FL	*971.00 FL
8	2		*FRONT FOG LAMP LH/RH	Broken (1 PCS ONLY)	686.00 FL	*343.00 FL
9	2		*FRONT FOG LAMP COVER LH/RH	Broken (1 PCS ONLY)	235.80 FL	*117.90 FL
10	1		*FRONT PANEL	Dented	1,227.50 FL	*1,227.50 FL
11	1		*FRONT PANEL LOWER CENTER	Dented	150.00 FL	*150.00 FL
12	2		*FRONT PANEL LOWER LH/RH	Dented (1 PCS ONLY)	620.00 FL	*310.00 FL
13	1		*CORNER PANEL RH	Dented	468.00 FL	*468.00 FL
14	1		*DASHBOARD REINFORCEMENT	Not Necessary	1,000.00 FL	*- FL
15	1		*AIR CON BLOWER MOTOR ASSY	Not Necessary	1,500.00 FL	*- FL
16	1		*HEATER UNIT ASSY	Not Necessary	3,980.00 FL	*- FL
17	1		*INTERCOOLER	Dented	3,360.70 FL	*2,121.60 FL
18	1		*INTERCOOLER GARNISH	Missing	324.70 FL	*138.10 FL
19	1		*CONDENSER & FAN ASSY	Not Necessary	2,300.00 FL	*- FL
20	1		*WIPER MOTOR	Not Necessary	415.00 FL	*- FL
21	1		*WIPER LINK ASSY	Not Necessary	550.00 FL	*- FL
22	1		*HEATER HOSE UNIT	Not Necessary	175.00 FL	*- FL
23	1		*HEATER HOSE OUTLET	Not Necessary	175.00 FL	*- FL
24	1		*AIR CON SUCTION HOSE	Not Necessary	440.00 FL	*- FL
25	1		*AIR CON DISCHARGE HOSE	Not Necessary	500.00 FL	*- FL
26	1		*DRIER RECEIVER	Not Necessary	520.00 FL	*- FL
27	1		*DRIVER DOOR (FRT RH)	Dented	1,285.70 FL	*1,285.70 FL
28	2		*DRIVER DOOR HINGES	Not Necessary	140.00 FL	*- FL
29	1		*DRIVER DOOR CHECKER	Not Necessary	70.00 FL	*- FL
30	1		*RH SLIDING DOOR	Dented	1,539.50 FL	*1,325.40 FL
31	1		*LH SLIDING DOOR	Dented	1,539.50 FL	*1,325.40 FL
32	1		*LH REAR FENDER	Dented	2,408.30 FL	*2,006.90 FL
33	1		*LH REAR HUB CAP	Broken	193.60 FL	*161.00 FL
34	1		*RH FRONT HUB CAP	Missing	193.60 FL	*161.00 FL
35	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
36	1		*RADIATOR GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
37	1		*FRONT NO PLATE	Broken	45.00 FS	*35.00 FS
38	1		*FRONT GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
39	1		*FRONT PANEL STICKER	Necessary	200.00 FS	*150.00 FS
40	1		*RH SLIDING DOOR STICKER	Necessary	320.00 FS	*200.00 FS
41	1		*LH REAR FENDER STICKER	Necessary	320.00 FS	*200.00 FS
42	1		*RHF RIM	Not Necessary	250.00 FS	*- FS
43	2		*HUB CAP	Not Necessary	240.00 FS	*- FS
44	1		*RADIATOR	Bent	1,560.00 FL	*716.10 FL
45	1		*COOLANT	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (\$)	34,022.50	15,544.80
					- List Item Discount on L Items 10.00/10.00% (\$)	3,241.75	1,484.98
					Total Parts (\$)	30,780.75	14,059.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT & WELD ON DAMAGED PANELS AND TO PANEL BEAT AND ALIGN ON LH REAR PANEL FRONT PANELS AND TO REPLACE DAMAGED PARTS	New	2,500.00	2,000.00
2	TO CHECK AND RECTIFY LIGHTING WIRE HARNESS	New	80.00	30.00
3	TO SPRAY PAINT RH SLIDING DOOR ,DRIVER DOOR ,LH REAR FENDER ,LH SLIDING DOOR ,FRONT BUMPER ,FRONT PANEL ,CORNER PANEL ,FLOOR PANEL AND AFFECTED AREAS	New	2,500.00	1,600.00
4	TO REMOVE AND REPLACE DRIVER DOOR PARTS AND MECHANISMS TO NEW DOOR	New	200.00	50.00
5	TO REMOVE AND REPLACE BOTH SLIDING DOOR PARTS AND MECHANISMS TO NEW DOOR	New	400.00	100.00
6	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS TO FACILITATE REPAIRS	New	150.00	120.00
7	TO RE-CHARGE AIR CON GAS	New	80.00	80.00
8	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
9	TO REMOVE AND REFIT UPHOLSTERY TO FACILITATE REPAIR	New	200.00	0.00
Gross Labour Cost (\$\$)			6,230.00	4,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >