

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002270/ENY3Q2**Date:** 25/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00079522100

Claimant Vehicle No : SMZ9733T **Insured Vehicle No :** YN8624C

Date of Loss: 09/03/2022 Nature of Claim: TP Claim No: SNM22D201678/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ9733T**

Make & Model: MERCEDES-BENZ GLB 180, 1.3 AMG LINE (A) Engine No: 28291480530270

Reg. Date: 28/05/2021 (Man. Year: 2021) Chassis No: W1N2476842W120686

Colour: Silver Odometer: 23054 km

Engine Capacity: 1332 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,377.35	7,968.68	1,408.67	15.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,400.00	5,280.00	2,120.00	28.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,777.35	13,248.68	3,528.67	21.03
+ GST 7.00/7.00% (S\$)	1,174.41	927.41	247.00	21.03
Nett Amount (S\$)	17,951.76	14,176.09	3,775.67	21.03

INSPECTION

Date of Assignment: 10/03/2022

Date Inspected: 17/05/2022 Inspected At: 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)
Repairer: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Aug 2022)

Parts: M1-SUV MERCEDES-BENZ GLB 180 1.3 AMG LINE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMZ9733T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER LOWER TRIM	Cut	502.44 FS	*502.44 FS
2	1		*REAR BUMPER	Dented	1,334.62 FS	*1,334.62 FS
3	1		*REAR BUMPER LOWER CHROME	Cut	1,181.20 FS	*1,181.20 FS
4	1		*REAR BUMPER STEP PLATE	Not Necessary	174.00 FS	*- FS
5	1		*REAR TOWING COVER	Broken	45.71 FS	*45.71 FS
6	1		*RH/BASIC CARRIER FOR BUMPER	Not Necessary	41.28 FS	*- FS
7	1		*RH/ REAR BUMPER LATERAL SUPPORT	Not Necessary	86.92 FS	*- FS
8	1		*TAILGATE	Dented	3,110.36 FS	*3,110.36 FS
9	1		*TAILGATE SEAL	Not Necessary	218.01 FS	*- FS
10	1		*REAR WINDSCREEN	Necessary	876.36 FS	*876.36 FS
11	2		*ONE-COMPONENT ADHESIVE	Necessary	358.62 FS	*358.62 FS
12	1		*MERCEDE STAR	Necessary	54.88 FS	*54.88 FS
13	3		*GROMMET	Necessary	8.10 FS	*8.10 FS
14	1		*MODEL PLATE	Necessary	87.52 FS	*87.52 FS
15	1		*RH/ OUTER REAR LAMP COMBINATION	Not Necessary	384.39 FS	*- FS
16	1		*RH /REAR LAMP COMBINATION	Broken	393.23 FS	*393.23 FS
17	1		*REAR CROSS MEMBER	Not Necessary	504.07 FS	*- FS
18	2		*ADHESIVE FILM CTING	Necessary	15.64 FS	*15.64 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **9,377.35** **7,968.68**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	3,840.00	1,920.00
2	RESPRAY TAILGATE & REAR BUMPER	New	1,800.00	1,600.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
4	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
5	REMOVE & TRANSFER TAILGATE MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR	New	400.00	400.00
6	REMOVE & REPLACE REAR WINDSCREEN WITH INSTALL	New	560.00	560.00
7	SUPPLY & INSTALL 1 PC REAR WINDSCREEN SOLAR HUPER OPTIK FILM	New	300.00	300.00
Gross Labour Cost (\$\$)			7,400.00	5,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >