



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22002272/Eqy3e2	
			Date: 22/06/2022	
			Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLB 1515Y	Veh. Inspected	SMX 3671M
	Policy No.		Coverage (\$)	0.00
	Claim No.	2022 22003989FR	Excess (\$)	0.00
	Assign From	Shanti	Assign Date	10/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	KIA CERATO	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	KNAF3416ML5070153	Colour	BLACK
	Odometer	62608 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	GOODYEAR	5 mm
	L/H Front Tyre	205/55 R16	GOODYEAR	5 mm
	R/H Rear Tyre	205/55 R16	GOODYEAR	5 mm
	L/H Rear Tyre	205/55 R16	GOODYEAR	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/02/2022	Inspection Date	10/03/2022
	Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	