

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22002276/Vty3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 13/04/2022 SINGAPORE 068811 ATTN: TEO KITTY Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) GBL 6444B Insured Veh. YN 8023L Veh. Inspected Policy No. P2394699 Coverage (\$) 0.00 Claim No. S2M03VDY Excess (\$) 0.00 **TEO KITTY Assign Date** 10/03/2022 Assign From **Vehicle Particulars & Condition** 2. TOYOTA HIACE DX Make & Model 2754 C.C HIDDEN 2021 Engine No. Year of Reg. GDH2012020570 SILVER Chassis No. Colour Odometer 8172 KM Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 198/80 R15 BRIDGESTONE 5 mm L/H Front Tyre 198/80 R15 BRIDGESTONE 5 mm 190/80 R15 BRIDGESTONE R/H Rear Tyre 5 mm BRIDGESTONE L/H Rear Tyre 190/80 R15 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 09/03/2022 Inspect Date / Time 11/03/2022 (02:08 PM) Accident Date SPEEDWERKZ PTE LTD Survey held at 13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Report Ref No. CS3/ASM22002276/Vty3e2

Estimate Days of Repair

Inspected By

5b.

THEVAN THOMAS KARTHIKESAVAN

ESTIMATED NORMAL PERIOD FOR REPAIR:

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days