

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE I	PTE LTD	Ref:	CS3/ASM22002277/Vqy3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	Date:	30/03/2022	
	ATTN: HO WINNIE		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 3672A	Veh. Inspected	FBH 5417H	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S2M03STI	Excess (\$)	0.00	
	Assign From	HO WINNIE	Assign Date	10/03/2022	
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA FZ 16	c.c	153	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	ME121C0G5D2011742	Colour	BLUE	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	100/80-17	BRIDGESTONE	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	100/80-17	BRIDGESTONE	5 mm	
	L/H Rear Tyre			mm	
4. Description of Damages					
	THE VEHICLE SUS PORTION.	USTAINED DAMAGES AT THE O/S BODY AND FRONT			
5.	5. General Information				
	Accident Date	04/02/2022	Inspect Date / Time	11/03/2022 (04:00 PM)	
	Survey held at SPEEDWERKZ PTE LTD				
	13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807				
5a.	5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM22002277/Vqy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

Tu

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser