

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22002280/EEA3Q2**Date:** 16/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SHA9515Y **Insured Vehicle No :** SLN6080M

Date of Loss: 07/03/2022 Nature of Claim: TP Claim No: MFL2022D0001532

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA9515Y**

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZRS047334

Reg. Date: 22/06/2017 (Man. Year: 2017) Chassis No: JTDKB3FU903558443

Colour: Yellow Odometer: 692509 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Goodyear 4 mm Rear Left Side: Goodyear 4 mm

Front Right Side: Goodyear 4 mm Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,629.90	4,638.42	4,991.48	51.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,950.00	1,670.00	3,280.00	66.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,579.90	6,308.42	8,271.48	56.73
Approved Total (Overridden) (S\$)		5,050.00		
(S\$)	14,579.90	5,050.00	9,529.90	65.36
+ GST 7.00/7.00% (S\$)	1,020.59	353.50	667.09	65.36
Nett Amount (S\$)	15,600.49	5,403.50	10,196.99	65.36
+ Loss of Use (7.5 x S\$40.00/day) (S\$)		300.00		
+ Car Rental (7.5 x S\$117.20/day) (S\$)		879.00		
Nett Liability (S\$)		6,582.50		
Global Sum Settlement (S\$)		6,550.00		

INSPECTION

Date of Assignment: 10/03/2022

Date Inspected: 10/03/2022 Inspected At: Ding Automotive Pte Ltd (HQ)
31 CORPORATION ROAD
Singapore 649825

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2022)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA9515Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Broken	516.00 FL	*516.00 FL
2	1		*FRONT LH BUMPER RETAINER	Broken	82.30 FL	*82.30 FL
3	1		*FRONT BUMPER ENERGY ABSORBER	Broken	79.60 FL	*79.60 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	716.60 FL	*- FL
5	1		*FRONT BUMPER LOWER REINFORCEMENT	Not Necessary	246.10 FL	*- FL
6	1		*FRONT LH BUMPER LOWER REINFORCEMENT BRACKET	Not Necessary	120.10 FL	*- FL
7	1		*RADIATOR GRILLE	Not Necessary	346.00 FL	*- FL
8	1		*RADIATOR GRILLE EMBLEM	Necessary	90.80 FL	*90.80 FL
9	1		*FRONT LH BUMPER TOWING COVER	Missing	29.30 FL	*29.30 FL
10	1		*FRONT BUMPER LICENCE PLATE MOULDING	Not Necessary	103.40 FL	*- FL
11	1		*FRONT LH FOG LAMP	Broken	951.40 FL	*951.40 FL
12	1		*RADIATOR GRILLE LOWER NO.1	Cut	170.10 FL	*170.10 FL
13	1		*FRONT BUMPER LOWER ABSORBER	Not Necessary	132.70 FL	*- FL
14	1		*FRONT LH HEADLAMP COMPUTER	Not Necessary	960.50 FL	*- FL
15	1		*FRONT LH HEADLAMP	Broken	2,637.60 FL	*2,637.60 FL
16	1		*FRONT LH HEADLAMP BRACKET	Not Necessary	34.80 FL	*- FL
17	1		*FRONT LH HEADLAMP PANEL	Repair	78.90 FL	*- FL
18	1		*BASE BATTERY TRAY	Not Necessary	115.50 FL	*- FL
19	1		*RADIATOR GRILLE UPPER COVER	Not Necessary	235.30 FL	*- FL
20	1		*FRONT LH FENDER PANEL	Dented	977.80 FL	*977.80 FL
21	1		*FRONT LH FENDER LINER	Torn	202.50 FL	*202.50 FL
22	1		*FRONT LH FENDER EMBLEM	Necessary	54.60 FL	*54.60 FL
23	1		*FRONT LH FENDER QUARTER GARNISH	Missing	100.40 FL	*100.40 FL
24	1		*SIDE SKIRT LH	Not Necessary	594.80 FL	*- FL
25	1		*FRONT LH DOOR PANEL	Repair	1,300.70 FL	*- FL
26	1		*FRONT LH WINDSCREEN MOULDING	Broken	85.50 FL	*85.50 FL
27	1		*ENGINE UNDER COVER (SMALL)	Not Necessary	241.90 FL	*- FL
28	1		*FRONT LH FENDER APRON MUDGUARD SEAL	Not Necessary	51.90 FL	*- FL
29	1		*FRONT LH SIDE MIRROR COVER	Not Necessary	76.10 FL	*- FL
30	1		*SET FRONT BUMPER CLIP	Necessary	75.00 FS	*20.00 FS
31	1		*FRONT BUMPER RETAINER CLIP	Necessary	55.00 FS	*10.00 FS
32	1		*SET RADIATOR GRILLE CLIP	Not Necessary	55.00 FS	*- FS
33	1		*FRONT LICENCE PLATE NUMBER WITH FRAME	Not Necessary	100.00 FS	*- FS
34	1		*SET FRONT FENDER LINER CLIP	Necessary	65.00 FS	*25.00 FS
35	1		*FRONT FENDR QUARTER GARNISH CLIP	Necessary	55.00 FS	*10.00 FS
36	1		*SET SIDE SKIRT CLIP	Not Necessary	55.00 FS	*- FS
37	1		*FRONT DOOR COMFORT DELGRO STICKER	Necessary	150.00 FS	*80.00 FS
38	1		*RADIATOR GRILLE UPPER COVER CLIP	Not Necessary	55.00 FS	*- FS
39	1		*BATTERY	Not Necessary	350.00 FS	*- FS
40	1		*FRONT WINDSCREEN MOULDING CLIP	Necessary	55.00 FS	*10.00 FS
41	1		*SET ENGINE UNDER COVER CLIP	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,463.20	6,132.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,833.30	1,494.48
Total Parts (\$\$)	9,629.90	4,638.42

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	New	1,600.00	500.00
2	TO RUST PROOFING OF THE AFFECTED AREA	New	170.00	30.00
3	TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	350.00	0.00
4	TO DIAGNOSTIC CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	New	300.00	120.00
5	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	New	150.00	0.00
6	TO READJUST AND REALIGN HEADLAMP AIM	New	130.00	20.00
7	TO RESPRAY FRONT BUMPER	New	250.00	200.00
8	TO RESPRAY FRONT BONNET	New	250.00	200.00
9	TO RESPRAY FRONT FENDER PANEL	New	250.00	200.00
10	TO RESPRAY FRONT FENDER APRON PANEL	New	250.00	0.00
11	TO RESPRAY FRONT SIDE MIRROR	New	250.00	0.00
12	TO RESPRAY FRONT DOOR PANEL	New	250.00	200.00
13	TO RESPRAY SIDE SKIRT LH	New	250.00	0.00
14	TO RESPRAY FRONT WHEEL RIM	New	250.00	0.00
15	TO RESPRAY HEADLAMP PANEL LH	New	250.00	200.00
Gross Labour Cost (\$\$)			4,950.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >