3/21/22, 9:14 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI22002284/KVCN2

Date: 21/03/2022

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MT100716

Claimant Vehicle SHF570U Insured Vehicle No: SLX7761Y

Date of Loss: 08/03/2022 Nature of Claim: TP Claim No: M2201163

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHF570U

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2H11593

Reg. Date: 30/09/2021 (Man. Year: 2020) Chassis No: JTDKB3FU903092481

Colour: Metallic Pearl White/Red Odometer: 36899 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Dunlop 3 mm Rear Left Side: Dunlop 2 mm
Front Right Side: Dunlop 3 mm Rear Right Side: Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,346.02	1,933.57	4,412.45	69.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,290.00	805.00	9,485.00	92.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,636.02	2,738.57	13,897.45	83.54
+ GST 7.00/7.00% (S\$)	1,164.52	191.70	972.82	83.54
Nett Amount (S\$)	17,800.54	2,930.27	14,870.27	83.54

INSPECTION

Date of Assignment: 11/03/2022

Trans-Cab Services Pte Ltd (HQ)

Date Inspected: 10/03/2022 Inspected At: 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.5 days

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/21/22, 9:14 AM Adjuster Report

Different 1 cents -Finalise confirm amount: \$2,738.58

REPAIR DETAILS

		ce

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Mar 2022)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHF570U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REINFORCEMENT SUB-ASSY,REAR BUMPER	Bent	332.70 FL	-	*332.70 F
2	1		*COVER,REAR BUMPER LOWER	Dented	22.00 FL	-	*22.00 FI
3	1		*GUARD,REAR BUMPER CENTER	Dented	374.50 FL	-	*374.50 F
4	1		*RETAINER,REAR BUMPER SIDE,LH	Serviceable	132.60 FL	-	*- FI
5	1		*RETAINER,REAR BUMPER SIDE,RH	Distorted	132.60 FL	-	*132.60 F
6	1		*PANEL SUB-ASSY,BACK DOOR	Repair	1,147.80 FL	-	*- FI
7	1		*PLATE LUGGAGE COMPARTMENT DOOR NAME NO 2	Necessary	54.60 FL	-	*54.60 F
8	1		*PLATE BACK DOOR NAME NO 1	Necessary	54.60 FL	-	*54.60 FI
9	1		*ORNAMENT SUB-ASSY,BACK DOOR	Necessary	47.90 FL	-	*47.90 FI
10	1		*GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	Mtg Cracked	913.60 FL	_	*913.60 F
11	1		*BOARD ASSY,BACK DOOR TRIM	Serviceable	259.20 FL	_	*- F
12	1		*WEATHERSTRIP,BACK DOOR	Serviceable	372.30 FL	_	*- FI
13	1		*COVER,DECK TRIM,REAR	Serviceable	126.70 FL	_	*- F
14	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	651.00 FL	_	*- FI
15	1		*STAY ASSY,BACK DOOR,LH	Serviceable	242.50 FL	_	*- F
16	1		*STAY ASSY,BACK DOOR,RH	Serviceable	242.50 FL	_	*- FI
17	1		*HINGE ASSY,BACK DOOR,LH	Repair	61.00 FL	_	*- F
18	1		*HINGE ASSY,BACK DOOR,RH	Repair	61.00 FL	_	*- FI
19	1		*SET PARKING AID	Serviceable	700.00 FS	_	*- F
20	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS		*60.00 F
21	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS		*- F
22	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	-	*- F
23	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	-	*- F
24	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	-	*30.00 F
25	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	-	*30.00 F
26	1		*REAR BUMPER PROTECTOR	No such part	180.00 FS	-	*- F
27	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	-	*- F
28	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	-	*- F
29	1		*SET BUMPER CLIP FRT	Not Necessary	95.00 FS	-	*- F
30	1		*REAR NUMBER PLATE WITH MOULDING	Not Necessary	200.00 FS	-	*- F
31	1		*COVER,REAR BUMPER	Buckled	485.60 FL	-	*485.60 F
F=Fra	ınchise	part. S=S	SpcNett. L=ListItemDisc.		-		
			- List Item Discount on L Items 25.	Sub Total (S\$) 00/25.00% (S\$)	-	2,538.10 604.53	
			-	Гotal Parts (S\$)	6,346.02		1,933.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,200.00	300.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
6	TO REMOVE AND REFIT ELECTRICAL WIRING,BAEETRY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
7	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
8	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
9	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
12	TOWING FEES	New	150.00	0.00
13	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	440.00
14	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
15	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
16	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
17	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	220.00	0.00
18	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
19	TO LIFT-UP/OUT ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
20	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS-MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	New	380.00	0.00
21	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
	Gross Labour	Cost (S\$)	10,290.00	805.00
	Report was unsubmitted during this p	orint-out		
	. topon mad undahimida daring tino p			

< END OF ESTIMATES >