



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 6366D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	STEERING GEAR (SN)	BENT	7,544.01	7,544.01
2	COMBINATION NUT (SN)	NOT NECESSARY	29.28	-
1	MOUNTING PLATE (SN)	NOT NECESSARY	16.93	-
1	INTEGRAL CARRIER (SN)	BENT	2,497.57	2,497.57
1	RH/FRONT SHOCK-ABSORBER STRUT (SN)	BENT	756.11	756.11
1	RH/FRONT UPPER CONTROL ARM (SN)	BENT	844.91	844.91
1	RH/FRONT STEERING KNUCKLE (SN)	BENT	1,410.99	1,410.99
1	RH/FRONT WHEEL BEARING (SN)	NECESSARY	562.47	562.47
1	RH/FRONT STRUT ROD (SN)	BENT	634.59	634.59
1	RH/FRONT SPRING LINK (SN)	BENT	631.45	631.45
1	NUT W FLANGE, BINDING (SN)	NECESSARY	9.80	9.80
2	NUT-A-WASHER ASSEMBLY (SN)	NECESSARY	31.36	31.36
1	RH/FRONT DISK WHEEL (SN)	CUT	641.32	641.32
1	RH/FRONT FENDER (SN)	DENTED	955.58	955.58
1	SEAM SEAL (SN)	NECESSARY	64.24	64.24
1	RH/HEADLAMP UNIT (SN)	NOT NECESSARY	3,366.07	-
1	HEXAGON HEAD BOLT (SN) (ADDITIONAL)	NECESSARY	17.69	17.69
2	THREAD ROLLING SCREW (SN) (ADDITIONAL)	NECESSARY	17.60	17.60
2	SCREW (SN) (ADDITIONAL)	NECESSARY	67.28	67.28
2	SCREW W RND. HEXAL. HEAD (SN) (ADDITIONAL)	NECESSARY	33.74	33.74
2	SCREW W RND. HEXAL. HEAD (SN) (ADDITIONAL)	NECESSARY	46.62	46.62
			20,179.61	16,767.33
<b><u>LABOUR</u></b>				
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.			1,440.00	960.00
RESPRAY RH/FRONT FENDER.			960.00	800.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.			380.00	380.00
TO REMOVE / REPLACE RH / FRONT AFFECTED SUSPENSION WITH ENGINE CARRIER.			2,400.00	1,920.00
ATTACH/DETACH ENGINE SUPPORT FIXTURE FOR NECESSARY REPAIRS.			480.00	480.00

Report Ref No. CS/UOI22002297/Eqy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO INSPECT & CONDUCT WHEEL ALIGNMENT.		540.00	540.00
	LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD.		60.00	60.00
	CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM.		180.00	180.00
	BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS / COMPONENTS.		120.00	120.00
	TO REMOVE, REPLACE HEADLAMP WITH FOCUS.		120.00	120.00
	TOWING FEE.		120.00	120.00
			6,800.00	5,680.00
<b>GRAND TOTAL</b>			<b>26,979.61</b>	<b>22,447.33</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>22,447.33</b>
<b>LESS EXCESS</b>				<b>-800.00</b>
<b>NETT LIABILITY</b>				<b>21,647.33</b>

Report Ref No. CS/UOI22002297/Eqy3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.