

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE PTE LTD			Ref:	CS3/ASM22002302/Rvy3e2
	8 SHENTON WAY SINGAPORE 0688		Date:	16/03/2022	
	ATTN: LOH CYNTH	AIF		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 2608Z	Veh. Inspected		SNB 3649H
	Policy No.		Coverage (\$)		0.00
	Claim No.	S2M03V5M	Excess (\$)		0.00
	Assign From	LOH CYNTHIA	Assign Date		11/03/2022
2.	Vehicle Particulars & Condition				
	Make & Model	JEEP WRANGLER UNLIMITED	c.c		1995
	Engine No.	HIDDEN	Year of Reg.		2021
	Chassis No.	1C4HJXLN2MW690191	Colour		RED
	Odometer	6370 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	305/70 R17	тоуо		8 mm
	L/H Front Tyre	305/70 R17	TOYO		8 mm
	R/H Rear Tyre	305/70 R17	тоуо		8 mm
	L/H Rear Tyre	305/70 R17	TOYO		8 mm
4.	Description of Damages				
	THE VEHICLE SUS	E SUSTAINED DAMAGES AT THE REAR O/S PORTION.			
5.	General Information				
	Accident Date	05/03/2022	Inspect Date /	Time	14/03/2022 (12:23 PM)
	Survey held at	160 Sin Ming Drive #06-10, S M	Autocity, 575722		
	Repairer	LIAN HENG PAINTER CO.			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				

Report Ref No. CS3/ASM22002302/Rvy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE