

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22002307/APA3Q2**Date:** 03/10/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SLN3122X **Insured Vehicle No :** SMM4926E

Date of Loss: 07/03/2022 Nature of Claim: TP Claim No: MFL2022D0001527

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN3122X**
 Make & Model: SUBARU FORESTER, 2.0 XT CVT AWD SR (A) Engine No: FA20B984361
 Reg. Date: 28/04/2017 (Man. Year: 2017) Chassis No: JF1SJGK85HG088633
 Colour: Black Odometer: 81327 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/50 R18 Rear Tyre Size: 255/50 R18
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,321.36	13,893.28	26,428.08	65.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,020.00	4,660.00	6,360.00	57.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	51,341.36	18,553.28	32,788.08	63.86
Approved Total (Overridden) (S\$)		14,250.00		
Nett Amount (S\$)	51,341.36	14,250.00	37,091.36	72.24
+ Car Rental (20.0 x S\$120.00/day) (S\$)		2,400.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		310.00		
Nett Liability (S\$)		16,996.45		
Global Sum Settlement (S\$)		17,000.00		

INSPECTION

Date of Assignment: 11/03/2022

Date Inspected: 14/03/2022 Inspected At:

SR AUTOWORKS PTE LTD (HQ)
 8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit #02-24
 Singapore 415875

Estimated Period of Repair: 15.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Jun 2022)

Parts: M1-SUV SUBARU FORESTER 2.0 XT CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLN3122X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	892.40 FL	*892.40 FL
2	2		*BONNET SIDE SEAL	Not Necessary	82.00 FL	*- FL
3	1		*BONNET CHROME	Not Necessary	244.00 FL	*- FL
4	1		*BONNET GRILLE LOGO	Not Necessary	189.00 FL	*- FL
5	1		*BONNET LOCK	Not Necessary	316.00 FL	*- FL
6	1		*HEAD LAMP	N/s Cracked	5,064.00 FL	*2,380.00 FL
7	1		*HEAD LAMP LOWER RETAINER	N/s Cracked	532.00 FL	*68.00 FL
8	1		*FRONT GRILLE	Not Necessary	580.00 FL	*- FL
9	1		*FRONT GRILLE CHROME	Not Necessary	265.30 FL	*- FL
10	1		*FRONT BUMPER	Distorted	760.00 FL	*760.00 FL
11	1		*FRONT BUMPER SIDE RETAINER	N/s Smashed	154.00 FL	*45.00 FL
12	1		*FRONT BUMPER TOP SEAL	Not Necessary	121.00 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	620.00 FL	*- FL
14	1		*FRONT BUMPER SEAL	Not Necessary	189.00 FL	*- FL
15	1		*FRONT BUMPER SPRAY NOZZLE LH	Not Necessary	366.20 FL	*- FL
16	1		*FRONT BUMPER SPRAY NOZZLE COVER LH	Not Necessary	67.00 FL	*- FL
17	1		*FRONT BUMPER SPRAY NOZZLE PIPE LH	Not Necessary	216.00 FL	*- FL
18	1		*FRONT BUMPER TOW COVER LH	Not Necessary	65.00 FL	*- FL
19	1		*FRONT BUMPER LOWER ABSORBER	Not Necessary	425.00 FL	*- FL
20	1		*FRONT AIR DUCT	Not Necessary	184.00 FL	*- FL
21	1		*AIR CLEANER BOX	Not Necessary	589.00 FL	*- FL
22	1		*FOG LAMP LH	Not Necessary	320.00 FL	*- FL
23	1		*FOG LAMP BRACKET LH	Not Necessary	154.00 FL	*- FL
24	1		*FOG LAMP TOP MOULDING LH	Not Necessary	166.00 FL	*- FL
25	1		*WIPER GARNISH	Not Necessary	685.00 FL	*- FL
26	1		*SUPPORT PANEL	Repair	876.00 FL	*- FL
27	1		*BRACE PANEL	Not Necessary	130.00 FL	*- FL
28	2		*HORN	Not Necessary	240.00 FL	*- FL
29	1		*AIR CON CONDENSER	Not Necessary	856.00 FL	*- FL
30	1		*RADIATOR	Not Necessary	910.00 FL	*- FL
31	1		*RADIATOR FAN COWLING	Not Necessary	219.00 FL	*- FL
32	1		*RESULATOR BOX	Not Necessary	542.00 FL	*- FL
33	1		*FRONT WHEEL HOUSING LH	Repair	766.00 FL	*- FL
34	1		*FRONT FENDER LH	Distorted	689.00 FL	*689.00 FL
35	1		*FRONT FENDER INNER BRACKET LH	Bent	215.00 FL	*215.00 FL
36	1		*FRONT FENDER TOP TRIM LH	Torn	214.00 FL	*214.00 FL
37	1		*FRONT FENDER COWLING LH	Torn	198.00 FL	*198.00 FL
38	1		*FRONT FENDER LOWER ARCH GARNISH LH	Deformed	124.00 FL	*124.00 FL
39	1		*FRONT ABSORBER LH	Bent	455.00 FL	*345.00 FL
40	1		*FRONT LOWER ARM LH	Bent	548.00 FL	*548.00 FL
41	1		*FRONT KNUCKLE ARM LH	Damaged	985.00 FL	*395.00 FL
42	1		*FRONT WHEEL BEARING LH	Damaged	214.40 FL	*214.40 FL
43	1		*STEERING RACK AND PINION	Cracked	2,145.00 FL	*1,980.00 FL
44	1		*TAIL GATE	Distorted	1,652.00 FL	*1,072.00 FL
45	1		*TAIL GATE LOGO	Necessary	93.00 FL	*93.00 FL
46	1		*TAIL GATE EMBLEM (SUBARU)	Necessary	98.00 FL	*98.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TAIL GATE EMBLEM (4WD)	Necessary	68.00 FL	*68.00 FL
48	1		*TAIL GATE EMBLEM (FORESTER)	Necessary	98.00 FL	*98.00 FL
49	1		*TAIL GATE WINDSCREEN WITH MOULDING	Not Necessary	1,254.00 FL	*- FL
50	1		*TAIL GATE OUTER GARNISH	Not Necessary	589.00 FL	*- FL
51	2		*TAIL GATE CAR PLATE LAMP	Not Necessary	288.00 FL	*- FL
52	1		*TAIL GATE CAR PLATE LAMP GARNISH	Not Necessary	255.60 FL	*- FL
53	1		*TAIL GATE OPENER SWITCH	Not Necessary	211.50 FL	*- FL
54	1		*TAIL GATE INNER LOCK	Jammed	281.70 FL	*281.70 FL
55	1		*TAIL GATE LOCK CATCH	Not Necessary	46.00 FL	*- FL
56	1		*TAIL GATE WEATHERSTRIP	Cut	262.15 FL	*262.15 FL
57	1		*TAIL GATE INNER TRIM	Cracked	394.20 FL	*394.20 FL
58	2		*TAIL GATE HINGE	Not Necessary	308.00 FL	*- FL
59	2		*TAIL GATE DAMPER ABSORBER	Not Necessary	531.80 FL	*- FL
60	1		*TAILLAMP	N/s Cracked	1,304.00 FL	*562.00 FL
61	2		*TAILLAMP SIDE PIN	Not Necessary	90.00 FL	*- FL
62	1		*TAIL LAMP LOWER BRACKET	N/s Cracked	330.00 FL	*65.00 FL
63	1		*REVERSE CAMERA ORG	Not Necessary	895.00 FL	*- FL
64	1		*REAR BUMPER	Distorted	690.00 FL	*690.00 FL
65	1		*REAR BUMPER SIDE RETAINER	N/s Damaged	240.00 FL	*45.00 FL
66	1		*REAR BUMPER REINFORCEMENT	Bent	370.00 FL	*370.00 FL
67	1		*REAR BUMPER REFLECTOR	N/s Cracked	288.00 FL	*144.00 FL
68	1		*REAR BUMPER TOW COVER	Missing	68.00 FL	*68.00 FL
69	1		*REAR BUMPER SIDE COVER RG	Damaged	56.00 FL	*56.00 FL
70	1		*REAR FENDER INNER TRIM	N/s Deformed	1,690.00 FL	*286.00 FL
71	2		*REAR FENDER INNER TRIM TOP	Not Necessary	970.00 FL	*- FL
72	2		*REAR FENDER INNER COWLING	Not Necessary	274.20 FL	*- FL
73	1		*REAR FENDER CONNER RUBBER SEAL	Not Necessary	154.00 FL	*- FL
74	1		*REAR END PANEL	Distorted	689.75 FL	*689.75 FL
75	1		*REAR END PANEL TOP GARNISH	Deformed	185.00 FL	*185.00 FL
76	1		*REAR FLOOR PANEL	Not Necessary	854.00 FL	*- FL
77	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	697.00 FL	*- FL
78	1		*REAR FLOOR PANEL SIDE BOARD	N/s Deformed	308.00 FL	*154.00 FL
79	1		*REAR FLOOR TOP SPONGE	Deformed	568.00 FL	*298.00 FL
80	2		*REAR FLOOR SIDE SPONGE	Not Necessary	1,082.00 FL	*- FL
81	1		*REAR EXHAUST PIPE	Not Necessary	954.00 FL	*- FL
82	2		*REAR EXHAUST MOUNTING	Not Necessary	132.00 FL	*- FL
83	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	167.00 FL	*- FL
84	1		*REAR EXHAUST CHROME HEAD	Not Necessary	211.00 FL	*- FL
85	1		*STEERING COUPLING	Damaged	544.00 FL	*544.00 FL
86	1		*FRONT RIM RH	Cut	996.00 FS	*600.00 FS
87	1		*FRONT NO PLATE	Not Necessary	100.00 FS	*- FS
88	1		*SET FRONT GRILLE CLIP	Not Necessary	30.00 FS	*- FS
89	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
90	1		*BONNET SEALANT	Not Necessary	60.00 FS	*- FS
91	1		*SET FRONT BUMPER UNDER COVER CLIP	Not Necessary	40.00 FS	*- FS
92	1		*SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
93	1		*RADIATOR COOLANT	Not Necessary	120.00 FS	*- FS
94	1		*FRONT AIR DUCT CLIPS	Not Necessary	30.00 FS	*- FS
95	1		*WHEEL HOUSING SEALANT	Not Necessary	80.00 FS	*- FS
96	1		*FRONT FENDER SEALANT	Not Necessary	60.00 FS	*- FS
97	1		*FRONT FENDER TOP TRIM CLIPS	Necessary	50.00 FS	*20.00 FS
98	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	50.00 FS	*30.00 FS
99	1		*WHEEL TYRE	Punctured	550.00 FS	*220.00 FS
100	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
101	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
102	4		*TAIL LAMP CLIP	Necessary	48.00 FS	*20.00 FS
103	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
104	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*40.00 FS
105	1		*TAILGATE OUTER GARNISH CLIP	Necessary	40.00 FS	*20.00 FS
106	1		*SET TAIL GATE INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

10/3/22, 2:03 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	1		*REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
108	1		*REAR FENDER INNER TOP TRIM CLIPS	Necessary	50.00 FS	*20.00 FS
109	1		*REAR FENDER INNER COWLING CLIPS	Necessary	60.00 FS	*20.00 FS
110	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	40.00 FS	*10.00 FS
111	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
112	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
113	1		*REVERSE CAMERA	Not Necessary	650.00 FS	*- FS
114	1		*REVERSE SENSOR	Damaged	450.00 FS	*200.00 FS
115	1		*ROOF TOP MAT	Not Necessary	1,245.00 FL	*- FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					49,333.20	17,011.60
- List Item Discount on L Items 20.00/20.00% (S\$)					9,011.84	3,118.32
Total Parts (S\$)					40,321.36	13,893.28
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,600.00	700.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	700.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	150.00	30.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	250.00	60.00
5	REMOVE AND INSTALL FRONT UNDER CARRIAGE	New	650.00	220.00
6	TO CHECK FOUR WHEEL ALIGNMENT	New	150.00	80.00
7	REMOVE AND INSTALL RADIATOR AND REFILL COOLANT AND HIGH PRESSURE TEST	New	200.00	0.00
8	REMOVE AND INSTALL CONDENSER AND REFILL AIRCON GAS	New	200.00	0.00
9	REMOVE AND INSTALL SEAT BELT AND RE-SET SRS CONTROL UNIT	New	350.00	0.00
10	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,800.00	1,300.00
11	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,000.00
12	TUFF COAT	New	300.00	80.00
13	WIRING CHECK	New	120.00	30.00
14	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	400.00	80.00
15	REAR CHASSIS ALIGNMENT	New	600.00	0.00
16	TRANSFER TAILGATE MECHANISM	New	150.00	80.00
17	REMOVE AND REFIX TAILGATE WINDSCREEN	New	150.00	120.00
18	REMOVE AND REFIX REAR EXHAUST PIPE	New	150.00	80.00
19	REMOVE AND INSTALL REVERSE CAMERA AND TEST FUNCTION	New	200.00	50.00
20	REMOVE AND INSTALL REVERSE SENSOR AND CHECK FUNCTIONER	New	200.00	50.00
Gross Labour Cost (\$\$)			11,020.00	4,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >