4/6/22, 9:52 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EGI22002310/RTY3N2

06/04/2022 Date:

**REFERENCE** 

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

**Claimant Vehicle** SHF333M Insured Vehicle No: GBK9029C

No:

Date of Loss: 10/03/2022 Nature of Claim: TP Claim No: CDMCG22000439

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHF333M

TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) 2ZR2F43489 Make & Model: Engine No:

JTDKB3FU303089401 Reg. Date: 26/12/2019 (Man. Year: 2019) Chassis No:

Odometer: 142947 km Colour: Maroon

**Engine Capacity:** 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Rear Left Side: Sailun 6 mm Sailun 6 mm Front Right Side: Sailun 6 mm Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,986.50	971.18	5,015.32	83.78
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,659.00	1,130.00	1,529.00	57.50
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Ne	tt Amount (S\$)	8.645.50	2,101.18	6,544,32	75.70

**INSPECTION** 

Date of Assignment: 10/03/2022

Strides Automotive Services Pte Ltd (Woodlands) Date Inspected: 11/03/2022 Inspected At:

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 4.0 days

DENISE TAY KWEE CHENG Adjuster: MOHD RASUL Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/6/22, 9:52 AM Adjuster Report

#### **REPAIR DETAILS**

#### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2022)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHF333M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY,REAR DOOR,RH (DISC 25%)	Bent	1,294.90 F	*971.18 F
2	2		*PAD,RR BUMPER,RH & LH,3	Not Necessary	22.00 F	*- F
3	2		*PAD,RR BUMPER,RH & LH,2	Not Necessary	8.00 F	*- F
4	2		*PAD,RR BUMPER,RH & LH,1	Not Necessary	8.00 F	*- F
5	1		*RETAINER,RR BUMPER,RH	Not Necessary	132.60 F	*- F
6	1		*CHECK ASSY,REAR DOOR	Not Necessary	183.80 F	*- F
7	1		*WEATHERSTRIP-REAR DOOR RH	Not Necessary	180.10 F	*- F
8	1		*DOOR LOCK REAR,RH	Not Necessary	561.90 F	*- F
9	1		*HINGE ASSY,REAR DOOR,LOWER RH	Not Necessary	87.10 F	*- F
10	1		*HINGE ASSY,REAR DOOR,UPPER RH	Not Necessary	98.90 F	*- F
11	1		*DOOR REAR MOTOR ASSY,POWER WINDOW REGULATOR,RH	Not Necessary	926.00 F	*- F
12	1		*DOOR REAR WINDOW REGULATOR SUB-ASSY,RH	Not Necessary	206.70 F	*- F
13	1		*MEMBER SUB-ASSY,RAIL ROOT SIDE REAR RH	Not Necessary	288.50 F	*- F
14	1		*PATCH,SIDE PANEL REAR END,RH & LH	Not Necessary	33.70 F	*- F
15	1		*LINER,REAR FENDER,RH	Not Necessary	139.80 F	*- F
16	1		*DUCT ASSY,QUARTER VENT,RH & LH	Not Necessary	67.00 F	*- F
17	1		*WEATHERSTRIP,REAR DOOR OPENING TRIM,RH	Not Necessary	293.00 F	*- F
18	1		*COVER,RR BUMPER ASSY	Repair	485.60 F	*- F
19	1		*DOOR OUTER HANDLE REAR,RH	Repair	97.40 F	*- F
20	1		*PANEL SUB-ASSY,FENDER REAR RH	Repair	871.50 F	*- F
F=Fra	ınchise	part.				
				Total Parts (S\$)	5,986.50	971.18

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING AND BODY WORK	New	845.00	400.00
2	SPRAY PAINT	New	1,314.00	630.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	40.00
5	TO REPLACE SUNDRY PARTS	New	100.00	0.00
6	TO TRANSFER DOOR MECHANISM	New	120.00	60.00
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
		Gross Labour Cost (S\$)	2,659.00	1,130.00
	Report was unsub	mitted during this print-out.		

< END OF ESTIMATES >