

Case Details

Case Reference Number : TAX/03/22/2023
Type of Repair : Accident Repair
Vehicle Registration Number : SHF333M

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-17703-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : ERGO Insurance Pte Ltd
Accident Date and Time : 10/03/2022 03:40 AM
Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			COVER, RR BUMPER ASSY	1	485.60	485.60	25.00	364.20	Replace	1	0	Repair	R
Standard	Main			PAD, RR BUMPER, RH & LH, 3	2	11.00	22.00	25.00	16.50	Replace	0	0	Not Give	Xm
Standard	Main			PAD, RR BUMPER, RH & LH, 2	2	4.00	8.00	25.00	6.00	Replace	0	0	Not Give	Xm
Standard	Main			PAD, RR BUMPER, RH & LH, 1	2	4.00	8.00	25.00	6.00	Replace	0	0	Not Give	Xm
Standard	Main			RETAINER, RR BUMPER, RH	1	132.60	132.60	25.00	99.45	Replace	0	0	Not Give	Xm
Standard	Main			PANEL SUB-ASSY, REAR DOOR, RH	1	1,294.90	1,294.90	25.00	971.18	Replace	1	971.18	Replace	BT
Standard	Main			CHECK ASSY, REAR DOOR	1	183.80	137.85	25.00	137.85	Replace	0	0	Not Give	Xm
Standard	Main			WEATHERSTRIP, REAR DOOR RH	1	180.10	180.10	25.00	135.08	Replace	0	0	Not Give	Xm
Standard	Main			DOOR OUTER HANDLE REAR, RH	1	97.40	97.40	25.00	73.05	Replace	1	0	Repair	R
Standard	Main			DOOR LOCK REAR, RH	1	561.90	561.90	10.00	505.71	Replace	0	0	Not Give	Xm
Standard	Main			HINGE ASSY, REAR DOOR, LOWER RH	1	87.10	65.32	25.00	65.32	Replace	0	0	Not Give	Xm
Standard	Main			HINGE ASSY, REAR DOOR, UPPER RH	1	98.90	74.18	25.00	74.18	Replace	0	0	Not Give	Xm

Total Spare Part Cost 4,713.08

Lump Sum Discount (%) 0.00

Final Spare Part Cost 4,713.08

Surveyor Total 971.18

Lump Sum Dis (%) 0

Final Sur Total 971.18

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR, RH	1	926.00	926.00	10.00	833.40	Replace	0	0	Not Give	X11
Standard	Main			DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	1	206.70	206.70	25.00	155.02	Replace	0	0	Not Give	X11
Standard	Main			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	1	288.50	288.50	25.00	216.38	Replace	0	0	Not Give	X11
Standard	Main			PANEL SUB-ASSY, FENDER REAR RH	1	871.50	871.50	25.00	653.63	Replace	1	0	Repair	R
Standard	Main			PATCH, SIDE PANEL REAR END, RH & LH	1	33.70	33.70	25.00	25.28	Replace	0	0	Not Give	X11
Standard	Main			LINER, REAR FENDER, RH	1	139.80	139.80	25.00	104.85	Replace	0	0	Not Give	X11
Standard	Main			DUCT ASSY, QUARTER VENT, RH & LH	1	67.00	67.00	25.00	50.25	Replace	0	0	Not Give	X11
Standard	Main			WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	1	293.00	293.00	25.00	219.75	Replace	0	0	Not Give	X11
Total Spare Part Cost									4,713.08		Surveyor Total		971.18	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0	
Final Spare Part Cost									4,713.08		Final Sur Total		971.18	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	400	
Total:			845.00	400.00 /	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY DOOR HANDLE	180.00	30	
2	Main	TO RESPRAY RH REAR DOOR	378.00	200	
3	Main	TO RESPRAY REAR FENDER RH	378.00	200	
4	Main	TO RESPRAY REAR BUMPER	378.00	200	
Total:			1,314.00	630.00 /	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 Xm	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
3	Main	TO REPLACE SUNDRY PARTS	100.00	0 Xm	
4	Main	TO TRANSFER DOOR MECHANISM	120.00	60	
5	Main	TO TEST AND REFILL REVERSE SENSOR SYSTEM	120.00	0 Xm	
Total:			500.00	100.00 /	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,713.08	971.18
Total Labour Cost	845.00	400.00
Total Spray Painting	1,314.00	630.00
Other	500.00	100.00
Overall Total	7,372.08	2,101.18
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	2,101.18
Surveyor Approved Amount		2,101.18
No of Repair Days*	6	4
Remarks		PART BY PART REPAIR / RESURVEY BEFORE PAINT PHOTO.
Surveyor Name		Rasul

Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Survey Date: 13/07/2022
 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Save

Clear