

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22002317/VVY3E2

Date: 05/08/2022

REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC22P00041700
Claimant Vehicle No : GBK708K **Insured Vehicle No :** SLQ8135K
Date of Loss: 10/03/2022 Nature of Claim: TP Claim No: DMPC2200098H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK708K**
Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2860581
Reg. Date: 11/12/2019 (Man. Year: 2019) Chassis No: JTFAT35Y40K213749
Colour: White Odometer: 110263 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,736.05	5,026.12	9,709.93	65.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,340.00	1,330.00	4,010.00	75.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,076.05	6,356.12	13,719.93	68.34
Approved Total (Overridden) (S\$)		5,100.00		
Nett Amount (S\$)	20,076.05	5,100.00	14,976.05	74.60

INSPECTION

Date of Assignment: 14/03/2022
Date Inspected: 14/03/2022 Inspected At: 8 Kaki Bukit Avenue 4 #01-49 Premier @ Kaki Bukit
Estimated Period of Repair: 4.0 days Repairer: J.E.W Motor Pte Ltd (HQ)

Adjuster: Thevan Thomas Karthikesavan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Aug 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK708K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,137.10 FL	*1,137.10 FL
2	1		*TAILGATE DYNA STICKER	Necessary	61.00 FL	*61.00 FL
3	1		*TAILGATE LH SIDE HINGES	Serviceable	123.10 FL	*- FL
4	1		*TAILGATE LH CENTRE HINGE	Serviceable	123.10 FL	*- FL
5	1		*TAILGATE RH CENTRE HINGE	Dented	123.10 FL	*123.10 FL
6	1		*TAILGATE RH SIDE HINGE	Dented	123.10 FL	*123.10 FL
7	1		*TAILGATE RH FLIP LOCK	Dented	237.50 FL	*237.50 FL
8	1		*TAILGATE LH FLIP LOCK	Serviceable	237.50 FL	*- FL
9	1		*TAILGATE LOWER PANEL	Dented	473.00 FL	*473.00 FL
10	1		*TAILGATE LH RUBBER STOPPER	Serviceable	28.30 FL	*- FL
11	1		*TAILGATE LH RUBBER STOPPER BRACKET	Serviceable	129.30 FL	*- FL
12	1		*TAILGATE RH RUBBER STOPPER	Missing	28.30 FL	*28.30 FL
13	1		*TAILGATE RH RUBBER STOPPER BRACKET	Dented	129.30 FL	*129.30 FL
14	1		*RH TAILLAMP	Cracked	164.10 FL	*164.10 FL
15	1		*RH TAILLAMP PANEL	Serviceable	113.10 FL	*- FL
16	1		*LH TAILLAMP	Serviceable	164.10 FL	*- FL
17	1		*LH TAILLAMP PANEL	Serviceable	113.10 FL	*- FL
18	1		*RH SIDE GATE	Dented	1,409.80 FL	*1,409.80 FL
19	1		*LH SIDE GATE	Serviceable	1,409.80 FL	*- FL
20	1		*EXHAUST PIPE	Repair	494.40 FL	*- FL
21	1		*EXHAUST PIPE GASKET	Serviceable	33.00 FL	*- FL
22	1		*EXHAUST PIPE RUBBER HANGER BRACKET	Serviceable	38.40 FL	*- FL
23	1		*EXHAUST PIPE RUBBER HANGER	Missing	87.20 FL	*87.20 FL
24	1		*EXHAUST PIPE RUBBER HANGER BRACKET CLAMP	Serviceable	21.30 FL	*- FL
25	1		*SPARE TYRE CARRIAGE	Serviceable	325.70 FL	*- FL
26	2		*REAR NUMBER PLATE LAMP	Serviceable	137.40 FL	*- FL
27	1		*REAR NUMBER PLATE BRACKET	Serviceable	148.30 FL	*- FL
28	1		*TAILGATE ADVERTISEMENT STICKER	Necessary	550.00 FS	*100.00 FS
29	1		*TAILGATE 70KM/H STICKER	Necessary	28.00 FS	*28.00 FS
30	1		*TAILGATE 13PAX STICKER	Necessary	28.00 FS	*28.00 FS
31	1		*TAILGATE INNER ALUMINIUM PANEL	Dented	750.00 FS	*300.00 FS
32	1		*SET TAILGATE INNER ALUMINIUM PANEL RIVETS	Necessary	180.00 FS	*70.00 FS
33	1		*TAILGATE LOWER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*REAR NUMBER PLATE	Bent	70.00 FS	*40.00 FS
35	1		*REAR STEP BRACKET	Bent	780.00 FS	*480.00 FS
36	1		*REAR REVERSE SENSOR WITH BRACKET	Cut	400.00 FS	*200.00 FS
37	1		*RH SIDE GATE INNER ALUMINIUM PANEL	Serviceable	850.00 FS	*- FS
38	1		*SET RH SIDE GATE INNER ALUMINIUM PANEL RIVETS	Serviceable	230.00 FS	*- FS
39	1		*LH SIDE GATE INNER ALUMINIUM PANEL	Serviceable	850.00 FS	*- FS
40	1		*SET LH SIDE GATE INNER ALUMINIUM PANEL RIVETS	Serviceable	230.00 FS	*- FS
41	1		*REAR PLATFORM ALUMINIUM PANEL	Dented	1,250.00 FS	*800.00 FS
42	1		*SET REAR PLATFORM ALUMINIUM PANEL RIVETS	Serviceable	280.00 FS	*- FS
43	1		*SPARE TYRE (BIG)	Serviceable	450.00 FS	*- FS
44	1		*SPARE TYRE (SMALL)	Serviceable	320.00 FS	*- FS
45	1		*CANOPY REAR ENFORCEMENT BEAM RH	Serviceable	850.00 FS	*- FS
46	1		*CANOPY REAR ENFORCEMENT BEAM LH	Serviceable	850.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					16,639.40	6,019.50
- List Item Discount on L Items 25.00/25.00% (\$\$)					1,903.35	993.38
Total Parts (\$\$)					14,736.05	5,026.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO PROVIDE WORKMANSHIP CUT / WELD AND REPLACING OF PARTS	New	1,800.00	500.00
2	SPRAY PAINT ON AFFECTED AND CONSISTENT AREAS	New	1,500.00	500.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	120.00	30.00
4	APPLY RUST CHEMICAL ON AFFECTED AREAS	New	150.00	30.00
5	REMOVE AND REPLACE REAR REVERSE SENSORS	New	100.00	30.00
6	REMOVE AND REPLACE EXHAUST PIPE AND GASKET	New	220.00	40.00
7	REMOVE, REINSTALL AND REPLACE CANOPY ASSY FOR REPAIR. TO REPLACE AFFECTED ITEMS	New	800.00	100.00
8	REPLACE AND ALIGNMENT TAILGATE, SIDE GATES INNER ALUMINIUM PANELS AND RIVETS	New	650.00	100.00
Gross Labour Cost (\$)			5,340.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >