

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22002322/RVY3E2

Date: 31/05/2022

REFERENCE

Insured/Claimant: SPACE FORM DESIGN PTE LTD Policy No: DMCVSNA00150632101

Date of Loss: 07/03/2022

Nature of Claim: OD

Claim No: SNM22D201634/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK5959U	Engine No:	RZ4E105F90
Make & Model:	ISUZU NHR87AUE4AA, 1.9 D (M)	Chassis No:	JAANHR87EK7100279
Reg. Date:	09/12/2019 (Man. Year: 2019)	Odometer:	100463 km
Colour:	White		
Engine Capacity:	1898 cc		
Market Value/New Car Price:	S\$91,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R13 (D)
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 5/5 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,871.00	4,742.00	129.00	2.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	688.80	562.80	126.00	18.29
Paintwork Labour	389.59	327.31	62.28	15.99
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,949.39	5,632.11	317.28	5.33
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	5,949.39	5,132.11	817.28	13.74
+ GST 7.00/7.00% (S\$)	416.46	359.25	57.21	13.74
Nett Amount (S\$)	6,365.85	5,491.36	874.49	13.74

INSPECTION

Date of Assignment:	14/03/2022	Present Location:	Auto Insure Pte Ltd (HQ) (Woodlands)
Date Inspected:	14/03/2022	Inspected At:	Auto Insure Pte Ltd (HQ) (Woodlands)
			6 Marsiling Lane
			Singapore 739145
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 31 May 2022)	
Parts:	N/A	ISUZU NHR87AUE4AA 1.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK5959U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		2,680.00 F	*2,551.00 F
<u>Supplementary #1</u>						
2	1		*BLOWER CPL	Cracked	340.00 F	*340.00 F
3	1		*HEATER BLOWER	Cracked	1,500.00 F	*1,500.00 F
4	1		*L/DOOR MIRROR	Missing	70.00 F	*70.00 F
5	1		*SIDE MIRROR ROUND LH	Cracked	12.00 F	*12.00 F
6	1		*W/SCREEN LWR MLDG	Necessary	102.00 F	*102.00 F
7	1		*W/SCREEN MLDG LWR LH	Necessary	12.00 F	*12.00 F
8	1		*WASHER CONTAINER CPL	Deformed	155.00 F	*155.00 F
F=Franchise part.						
Total Parts (\$\$)					4,871.00	4,742.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR FOR SPRAY PAINTING	New	389.59	327.31
<u>Labour Items</u>				
2	LABOUR FOR PANEL BEATING	New	688.80	562.80
Gross Labour Cost (S\$)			1,078.39	890.11

Report was unsubmitted during this print-out.

< END OF ESTIMATES >