

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002329/AVY3N2**Date:** 26/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00016522100

**Claimant Vehicle
No :** SLU580P**Insured Vehicle
No :** SKM8303A

Date of Loss: 04/03/2022

Nature of Claim: TP

Claim
No: SNM22D201562/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLU580P**

Make & Model: VOLVO XC60, 3.0 T6 3.0L (A)

Engine No: B6304T05051016581

Reg. Date: 02/08/2010 (Man. Year: 2010)

Chassis No: YV1DZ9056B2135243

Colour: Gold

Odometer: 224080 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60R18	Rear Tyre Size:	235/60R18
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,357.40	4,675.50	15,681.90	77.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,150.00	610.00	4,540.00	88.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,507.40	5,285.50	20,221.90	79.28
Approved Total (Overridden) (\$\$)		4,200.00		
Nett Amount (\$\$)	25,507.40	4,200.00	21,307.40	83.53

INSPECTION

Date of Assignment: 14/03/2022

Date Inspected: 22/03/2022 Inspected At:

JL Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2022)
Parts:	M1-SUV	VOLVO XC60 3.0 T6 3.0L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU580P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER UPPER	Deformed	1,402.00 FL	*1,402.00 FL
2	1		*REAR BUMPER LOWER	Deformed	1,465.00 FL	*840.00 FL
3	1		*REAR BUMPER DIFFUSER	Deformed	873.00 FL	*550.00 FL
4	1		*REAR BUMPER INNER CENTER GARNISH	Cracked	390.00 FL	*285.00 FL
5	1		*REAR BUMPER UPPER CENTER GARNISH	Deformed	490.00 FL	*368.00 FL
6	2		*REAR BUMPER REFLECTOR	Not Necessary	480.00 FL	*- FL
7	1		*REAR BUMPER SENSOR	Damaged (2pcs only)	1,120.00 FL	*560.00 FL
		4 Pcs				
8	1		*REAR BUMPER REINFORCEMENT	Dented	1,480.00 FL	*1,190.00 FL
9	2		*REAR BUMPER SIDE RETAINER	Not Necessary	216.00 FL	*- FL
10	2		*TAIL LAMP	Not Necessary	1,792.00 FL	*- FL
11	2		*TAIL LAMP LOWER BRACKET	Not Necessary	340.00 FL	*- FL
12	1		*TAILGATE	Not Necessary	3,980.00 FL	*- FL
13	1		*TAILGATE EMBLEM XC60	Not Necessary	110.00 FL	*- FL
14	1		*TAILGATE EMBLEM T5	Not Necessary	60.00 FL	*- FL
15	2		*TAILGATE EMBLEM AWS	Not Necessary	122.00 FL	*- FL
16	1		*TAILGATE EMBLEM VOLVO	Not Necessary	260.00 FL	*- FL
17	1		*TAILGATE INNER LOCK	Not Necessary	580.00 FL	*- FL
18	1		*TAILGATE LOCK CATCH	Not Necessary	35.00 FL	*- FL
19	1		*TAILGATE WEATHER STRIP	Not Necessary	245.00 FL	*- FL
20	1		*REAR END PANEL TOP COVER PANEL	Not Necessary	545.00 FL	*- FL
21	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	1,460.00 FL	*- FL
22	1		*REAR EXHAUST	Not Necessary	3,760.00 FL	*- FL
23	1		*REAR EXHAUST INSULATOR	Not Necessary	425.00 FL	*- FL
24	4		*REAR EXHAUST MOUNTING	Not Necessary	156.00 FL	*- FL
25	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
26	1		*REAR BUMPER SECTION GARNISH CLIP (SET)	Not Necessary	60.00 FS	*- FS
27	1		*TAIL LAMP CLIP (SET)	Not Necessary	80.00 FS	*- FS
28	1		*TAIL LAMP LOWER GARNISH CLIP (SET)	Not Necessary	60.00 FS	*- FS
29	1		*REAR END PANEL SEALANT	Not Necessary	200.00 FS	*- FS
30	1		*REAR FENDER INNER COWLING RIVERT (SET)	Not Necessary	150.00 FS	*- FS
31	1		*REAR FENDER INNER TRIM CLIP (SET)	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	22,536.00	5,195.00
- List Item Discount on L Items 10.00/10.00% (\$)	2,178.60	519.50
Total Parts (\$)	20,357.40	4,675.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	New	1,600.00	300.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	250.00
3	TUFF COAT	New	250.00	0.00
4	WIRING AND BULB CHECK	New	180.00	0.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	150.00	60.00
7	TRANSFER TAILGATE MECHANISM	New	100.00	0.00
8	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
9	REMOVE AND REFIX TAIL GATE WINDSCREEN	New	150.00	0.00
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	650.00	0.00
Gross Labour Cost (\$)			5,150.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >