

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail: jlperfectautowork@gmail.com



DATE : 21.03.2022

TO : CHINA TAIPIING MOTOR CLAIMS DEPTS
VEHICLE NO : SLU580P
MODEL : VOLVO XC60
DATE OF ACCIDENT : 04.03.2022
TIME OF ACCIDENT : 06:45HRS

YV 1DZ9056B2135243

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER UPPER <i>del</i>	1	\$ 1,402.00	\$ 1,402.00
2	REAR BUMPER LOWER <i>del</i>	1	\$ 1,465.00	\$ 1,465.00
3	REAR BUMPER DIFFUSER <i>del</i>	1	\$ 873.00	\$ 873.00
4	REAR BUMPER INNER CENTER GARNISH <i>del</i>	1	\$ 390.00	\$ 390.00
5	REAR BUMPER UPPER CENTER GARNISH <i>del</i>	1	\$ 490.00	\$ 490.00
6	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 240.00	\$ 480.00
7	REAR BUMPER SENSOR <i>2 pieces del</i>	4	\$ 280.00	\$ 1,120.00
8	REAR BUMPER REINFORCEMENT <i>del</i>	1	\$ 1,480.00	\$ 1,480.00
9	REAR BUMPER SIDE RETAINER <i>not nec</i>	2	\$ 108.00	\$ 216.00
10	TAIL LAMP <i>3 not nec</i>	2	\$ 896.00	\$ 1,792.00
11	TAIL LAMP LOWER BRACKET	2	\$ 170.00	\$ 340.00
12	TAILGATE	1	\$ 3,980.00	\$ 3,980.00
14	TAILGATE EMBLEM 'XC60'	1	\$ 110.00	\$ 110.00
15	TAILGATE EMBLEM 'T5'	1	\$ 60.00	\$ 60.00
16	TAILGATE EMBLEM 'AWS'	2	\$ 61.00	\$ 122.00
16	TAILGATE EMBLEM 'VOLVO'	1	\$ 260.00	\$ 260.00
13	TAILGATE INNER LOCK	1	\$ 580.00	\$ 580.00
17	TAILGATE LOCK CATCH	1	\$ 35.00	\$ 35.00
18	TAILGATE WEATHER STRIP	1	\$ 245.00	\$ 245.00
20	REAR END PANEL TOP COVER PANEL <i>3 not nec</i>	1	\$ 545.00	\$ 545.00
21	REAR FLOOR PANEL TOP BOARD	1	\$ 1,460.00	\$ 1,460.00
22	REAR EXHAUST	1	\$ 3,760.00	\$ 3,760.00
23	REAR EXHAUST INSULATOR <i>not nec</i>	1	\$ 425.00	\$ 425.00
24	REAR EXHAUST MOUNTING	4	\$ 39.00	\$ 156.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SLU580P
 MODEL : VOLVO XC60
 DATE OF ACCIDENT : 04.03.2022
 TIME OF ACCIDENT : 06:45HRS

5195
 4675.50

TOTAL PRICE \$ 21,786.00
 LESS 10% \$ 2,178.60
 SUB TOTAL PRICE \$ 19,607.40

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Not Nec</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER SECTION GARNISH CLIP (SET) <i>Not Nec</i>	1	\$ 60.00	\$ 60.00
3	TAIL LAMP CLIP (SET)	1	\$ 80.00	\$ 80.00
4	TAIL LAMP LOWER GARNISH CLIP (SET) <i>X</i>	1	\$ 60.00	\$ 60.00
5	REAR END PANEL SEALANT <i>X</i>	1	\$ 200.00	\$ 200.00
6	REAR FENDER INNER COWLING RIVERT (SET) <i>Not Nec</i>	1	\$ 150.00	\$ 150.00
7	REAR FENDER INNER TRIM CLIP (SET) <i>Not Nec</i>	1	\$ 150.00	\$ 150.00

TOTAL \$ 750.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,600.00	300
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	250
3	TUFF COAT	\$ 250.00	X
4	WIRING AND BULB CHECK	\$ 180.00	X
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	X
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 150.00	60
7	TRANSFER TAILGATE MECHANISM	\$ 100.00	X
8	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
9	REMOVE AND REFIX TAIL GATE WINDSCREEN	\$ 150.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	X

TOTAL \$ 5,150.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SLU580P
MODEL : VOLVO XC60
DATE OF ACCIDENT : 04.03.2022
TIME OF ACCIDENT : 06:45HRS

ESTIMATE REPORT

TOTAL PARTS COST : \$20,357.40
TOTAL LABOUR COST : \$5,150.00
TOTAL REPAIR COST : \$25,507.40

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP: 8297 9787

Adrian Lj

h/s 22/03/22

03 days.

total: 528550

h/s: 42K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: