

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22002332/APA3Q2**Date:** 11/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100306345
Claimant Vehicle No :	SGD4799Z	Insured Vehicle No :	EU380H
Date of Loss:	13/03/2022	Nature of Claim:	TP
		Claim No:	7597095525SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGD4799Z	Engine No:	DAX046753
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Chassis No:	WAUZZZFY8J2240513
Reg. Date:	27/11/2018 (Man. Year: 2018)	Odometer:	33265 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,969.00	3,526.00	6,443.00	64.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,252.00	2,552.00	1,700.00	39.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	14,221.00	6,078.00	8,143.00	57.26
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	18/03/2022		
Date Inspected:	18/03/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,030.00 FS	*- FS
2	1		*REAR BUMPER LOWER COVER	Deformed	1,330.00 FS	*1,330.00 FS
3	1		*REAR BUMPER SPOILER	Deformed	966.00 FS	*966.00 FS
4	2		*REAR BUMPER TOWING EYE COVER -LH/RH	Not Necessary	87.00 FS	*- FS
5	2		*REAR BUMPER CLOSING ELEMENT -LH/RH	Not Necessary	216.00 FS	*- FS
6	2		*REAR BUMPER CHROME TRIM -LH/RH	Not Necessary	530.00 FS	*- FS
7	2		*TAIL LIGHT -LH/RH	Not Necessary	1,558.00 FS	*- FS
8	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,043.00 FS	*- FS
9	1		*REAR BUMPER HOLDING STRAP	Not Necessary	189.00 FS	*- FS
10	2		*REAR PARKING AID SENSOR	Not Necessary	530.00 FS	*- FS
11	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
12	2		*REAR WHEEL ARCH COVER -LH/RH	Necessary	1,230.00 FS	*1,230.00 FS
13	1		*SUNDRIES	*Check	250.00 FS	*- FS
Total Parts (\$)					9,969.00	3,526.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PART REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR UPPER BUMPER ,REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	New	2,500.00	1,500.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,252.00	2,552.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >