

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002333/EQY3N2**Date:** 13/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00037302207

**Claimant Vehicle
No :** SLG1127H**Insured Vehicle
No :** SKK6075G

Date of Loss: 04/03/2022

Nature of Claim: TP

Claim
No: SNM22D201566/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLG1127H**

Make & Model: BMW 320I, 2.0 MSPT LED HL LED FL (A)

Engine No: F3863637B48B20A

Reg. Date: 15/10/2020 (Man. Year: 2020)

Chassis No: WBA5F32070FJ63743

Colour: Black

Odometer: 27653 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50R17	Rear Tyre Size:	215/50R17
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,217.20	1,955.65	1,261.55	39.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,172.00	495.00	18.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,884.20	4,127.65	1,756.55	29.85
+ GST 7.00/7.00% (S\$)	411.89	288.94	122.95	29.85
Nett Amount (S\$)	6,296.09	4,416.59	1,879.50	29.85

INSPECTION

Date of Assignment: 14/03/2022

Date Inspected: 21/03/2022 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance
Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 May 2022)

Parts: 143 BMW 320I 2.0 MSPT LED HL LED FL (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLG1127H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER CARRIER	Dented	493.80 FS	*493.80 FS
3	1		*ADAPTER	Broken	48.35 FS	*48.35 FS
4	1		*REAR BUMPER LH SIDE GUIDE	Not Necessary	134.30 FS	*- FS
5	1		*REAR BUMPER RH SIDE GUIDE	Not Necessary	134.30 FS	*- FS
6	1		*SET MOUNTING PDC/PMA SENSOR REAR	Not Necessary	70.60 FS	*- FS
7	14		*EXPANDING RIVET D=8MM	Not Necessary	15.40 FS	*- FS
8	1		*REAR SILENCER HEAT INSULATION	Not Necessary	77.30 FS	*- FS
9	1		*REAR DIFFUSER	Broken	71.30 FS	*71.30 FS
10	2		*ULTRASONIC SENSOR MEDITERRANEAN BLU	Not Necessary	766.30 FS	*- FS
11	2		*DECOUPLING RING	Not Necessary	10.30 FS	*- FS
12	1		*(DG/SL) ADHESIVE SET K6	Not Necessary	53.05 FS	*- FS
13	1		*REAR BUMPER PANEL PRIMED (BASIS PDC)	Dented	1,262.20 FS	*1,262.20 FS
					Total Parts (S\$)	3,217.20 1,955.65

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER	New	1,038.00	986.00
3	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION.	New	177.00	168.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	168.00
Gross Labour Cost (\$\$)			2,667.00	2,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >