

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22002334/AEA3Q2**Date:** 27/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100498677-04
<b>Claimant Vehicle No :</b>	SJR8994R	<b>Insured Vehicle No :</b>	SLK6223J
Date of Loss:	29/12/2021	Nature of Claim:	TP
		Claim No:	1198648147SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJR8994R</b>		
Make & Model:	KIA CERATO FORTE, 1.6 SX AT ABS D/AB 2WD 4DR (A)	Engine No:	G4FC9H264202
Reg. Date:	20/07/2009 (Man. Year: 2009)	Chassis No:	KNAFH221395086989
Colour:	White	Odometer:	144818 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,367.00	880.00	1,487.00	62.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	580.00	430.00	150.00	25.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>2,947.00</b>	<b>1,310.00</b>	<b>1,637.00</b>	<b>55.55</b>
<b>+ Car Rental (2.0 x S\$100.00/day) (\$\$)</b>		200.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>1,517.45</b>		

INSPECTION

Date of Assignment:	29/03/2022		Premium Carz Services Pte Ltd (HQ)
Date Inspected:	29/03/2022	Inspected At:	1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki
Estimated Period of Repair:	2.0 days		Singapore 417883

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Not Necessary	560.00 FL	*- FL
2	1		*FRONT BUMPER INNER FOAM	Not Necessary	158.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	56.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	56.00 FL	*- FL
5	1		*FRONT BUMPER	Deformed	1,500.00 FS	*800.00 FS
6	10		*FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
7	1		*FRONT NUMBER PLATE W/CASING	Cracked	70.00 FS	*50.00 FS
					<b>Sub Total (\$\$)</b>	<b>2,450.00 880.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>83.00 0.00</b>
					<b>Total Parts (\$\$)</b>	<b>2,367.00 880.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	30.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	250.00	200.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	300.00	200.00
<b>Gross Labour Cost (\$)</b>			<b>580.00</b>	<b>430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >