



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2204623

INV Date 27/07/2022

Reference CC4/LPC22002337/Kga3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SGV 3288T
Insured Veh. GBF 3285U
Claim No. 21/22/22/VC00/025545
Policy No. Z/21/VC00/112247
Accident Date 11/03/2022
Inspection Date 15/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22002337/Kga3q2 Date: 27/07/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 3285U	Veh. Inspected	SGV 3288T	
Policy No.	Z/21/VC00/112247	Coverage (\$)	0.00	
Claim No.	21/22/22/VC00/025545	Excess (\$)	0.00	
Assign From		Assign Date	14/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E350 (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDD2130502A251923	Colour	GREY	
Odometer	68076 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R19	PIRELLI	3 mm	
L/H Front Tyre	245/40 R19	PIRELLI	3 mm	
R/H Rear Tyre	275/35 R19	PIRELLI	5 mm	
L/H Rear Tyre	275/35 R19	PIRELLI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/03/2022	Inspection Date	15/03/2022	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			1 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 3288T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	2,250.00	-
1	REAR BUMPER LOWER BUMPER	SERVICEABLE	445.00	-
1	REAR BUMPER LOWER CHROME MOULDING	SERVICEABLE	365.00	-
2	REAR BUMPER REVERSE SENSOR @\$220.00	SERVICEABLE	440.00	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	65.00	-
1	REAR EXHAUST TIP CHROME LH	SERVICEABLE	190.00	-
1	REAR EXHAUST TIP CHROME RH	SERVICEABLE	190.00	-
1	REAR REINFORCEMENT	TO REPAIR SEE LABOUR	600.00	-
1	END PANEL	TO REPAIR SEE LABOUR	750.00	-
1	END PANEL TOP COVER	SERVICEABLE	140.00	-
	LESS 10% DISCOUNT		-543.50	-
			4,891.50	-
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS (SN)	NOT NECESSARY	100.00	-
1	REAR END PANEL JOINT SEALANT (SN)	NOT NECESSARY	120.00	-
1	REAR BUMPER CHROME MOULDING CLIPS (SN)	NOT NECESSARY	40.00	-
1	END PANEL TOP COVER CLIPS (SN)	NOT NECESSARY	50.00	-
			310.00	-
<u>LABOUR</u>				
	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF REAR BUMPER, REAR REINFORCEMENT AND END PANEL.		700.00	80.00
	LABOUR CHARGES TO SUPPLY PAINT (SPECIAL COLOUR) ACCIDENT AREA.		700.00	250.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR.	NOT NECESSARY	120.00	-
	TO TUFF COAT AND UNDERSEAL MATERIAL.	NOT NECESSARY	120.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	NOT NECESSARY	100.00	-
			1,740.00	330.00
GRAND TOTAL			6,941.50	330.00
RECOMMENDED COST OF REPAIRS				330.00

Report Ref No. CC4/LPC22002337/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGV 3288T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGV 3288T

RE-INSPECTION

