3/28/22, 3:06 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22002343/KTY3E2

28/03/2022 Date:

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001962159

Claimant Vehicle SLW1044D Insured Vehicle No: SLV1681U No:

Date of Loss: 11/03/2022 Nature of Claim: ΤP Claim No: 271139

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW1044D**

Make & Model: KIA CERATO K3, 1.6 (A) G4FGHH687951 Engine No: Reg. Date: 30/01/2018 (Man. Year: 2017) Chassis No: KNAFX411MJ5755813

Colour: Metallic Black Odometer: 85102 km

Engine Capacity: 1591 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16 Front Left Side: Rear Left Side: Yokohama 8 mm Yokohama 8 mm Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,019.43	1,877.60	141.83	7.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,310.00	1,080.00	230.00	17.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S	\$) 3,329,43	2.957.60	371.83	11.17

INSPECTION

Date of Assignment: 14/03/2022

Rc Auto-160 Sin Ming (HQ)

160 SIN MING DRIVE, #06-20 SIN MING Date Inspected: 14/03/2022 Inspected At: **AUTOCITY**

Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG DENISE TAY KWEE CHENG Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Mar 2022)

Parts: 143 KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLW1044D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*REAR BUMPER	Bent	681.90 FL	*681.90 FL
1		*REAR BUMPER BEAM	Bent	331.30 FL	*313.00 FL
1		*REAR BUMPER LOWER COVER	Cracked	347.90 FL	*347.90 FL
1		*REAR BUMPER REFLECTOR (L/H)	Cut	79.10 FL	*79.10 FL
1		*REAR PANEL	Bent	379.60 FL	*379.60 FL
1		*REAR LEFT SIDE LOWER COVER	Cracked	62.50 FL	*62.50 FL
3		*REAR REINFORCEMENT BRACKET	Repair	50.40 FL	*- FL
1		*REVERSE SENSORS	Shorted	280.00 FS	*200.00 FS
nchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
			Sub Total (S\$)	2,212.70	2,064.00
		- List Item Discount on L Items 10.00/10.00% (S\$)			186.40
			Total Parts (S\$)	2,019.43	1,877.60
	1 1 1 1 1 1 3 1	1 1 1 1 1 1 3	1 *REAR BUMPER 1 *REAR BUMPER BEAM 1 *REAR BUMPER LOWER COVER 1 *REAR BUMPER REFLECTOR (L/H) 1 *REAR PANEL 1 *REAR LEFT SIDE LOWER COVER 3 *REAR REINFORCEMENT BRACKET 1 *REVERSE SENSORS anchise part. S=SpcNett. L=ListItemDisc.	1 *REAR BUMPER BEAM Bent 1 *REAR BUMPER BEAM Bent 1 *REAR BUMPER LOWER COVER Cracked 1 *REAR BUMPER REFLECTOR (L/H) Cut 1 *REAR PANEL Bent 1 *REAR LEFT SIDE LOWER COVER Cracked 3 *REAR REINFORCEMENT BRACKET Repair 1 *REVERSE SENSORS Shorted anchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)	1 *REAR BUMPER Bent 681.90 FL 1 *REAR BUMPER BEAM Bent 331.30 FL 1 *REAR BUMPER LOWER COVER Cracked 347.90 FL 1 *REAR BUMPER REFLECTOR (L/H) Cut 79.10 FL 1 *REAR PANEL Bent 379.60 FL 1 *REAR LEFT SIDE LOWER COVER Cracked 62.50 FL 3 *REAR REINFORCEMENT BRACKET Repair 50.40 FL 1 *REVERSE SENSORS Shorted 280.00 FS anchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) 2,212.70 - List Item Discount on L Items 10.00/10.00% (S\$) 193.27

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOWING FEES	New	60.00	0.00
2	SPRAY PAINTING	New	500.00	450.00
3	LABOUR TO RENEW ABOVE PARTS	New	700.00	600.00
4	ANTI RUST	New	50.00	30.00
		Gross Labour Cost (S\$)	1,310.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >