

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002347/EQY3N2**Date:** 17/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00013232102

Claimant Vehicle No : SMV1457P **Insured Vehicle No :** PC8852A

Date of Loss: 10/03/2022 Nature of Claim: TP Claim No: SNM22D201743/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV1457P**

Make & Model: RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A) Engine No: K9KF649D060539

Reg. Date: 17/09/2020 (Man. Year: 2020) Chassis No: VF1RFA00X64896755

Colour: Silver Odometer: 36034 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50R17 Rear Tyre Size: 215/50R17

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,523.31	7,408.62	3,114.69	29.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,830.00	3,630.00	3,200.00	46.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	17,353.31	11,038.62	6,314.69	36.39
+ GST 7.00/7.00% (\$\$)	1,214.73	772.70	442.03	36.39
Nett Amount (\$\$)	18,568.04	11,811.32	6,756.72	36.39

INSPECTION

Date of Assignment: 22/03/2022

Date Inspected: 25/04/2022 Inspected At: Wearnes Automotive Pte Ltd (Alexandra Road)
249 Alexandra Road
Singapore 159935

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 May 2022)

Parts: M1-MPV RENAULT GRAND SCENIC IV 1.5 DCI EU6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMV1457P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR GS4 BOSS	Crushed	1,000.10 FS	*900.09 FS
2	1		*TOWING COVER REAR BU	Crushed	91.40 FS	*82.26 FS
3	1		*BUMPER REAR PAD GS4	Cut	595.20 FS	*535.68 FS
4	1		*BUMPER REAR LOWER MO	Cut	615.40 FS	*553.86 FS
5	10		*BUMPER MOULDING CLIP	Necessary	40.00 FS	*36.00 FS
6	1		*BUMPER REAR CENTER B	Broken	384.00 FS	*345.60 FS
7	1		*BUMPER REAR PAD SUPP	Not Necessary	93.70 FS	*- FS
8	1		*TAILGATE OUTER PANEL	Broken	644.40 FS	*579.96 FS
9	10		*RIVET FIX P	Necessary	125.00 FS	*112.50 FS
10	1		*TAILGATE OUTER PANEL	Not Necessary	403.80 FS	*- FS
11	1		*LOGO REAR DIAMOND	Necessary	172.10 FS	*154.89 FS
12	1		*EMBLEM SCENIC GS4	Necessary	137.40 FS	*123.66 FS
13	1		*EMBLEM RENAULT REA	Necessary	108.40 FS	*97.56 FS
14	4		*PARKING SENSOR FRT/B	Not Necessary	1,094.00 FS	*- FS
15	1		*BUMPER REAR REINFORC	Dented	787.20 FS	*708.48 FS
16	1		*TAILGATE ASSY GS4	Broken	2,181.70 FS	*1,963.53 FS
17	1		*WINDSCREEN REAR GS4	Necessary	792.10 FS	*712.89 FS
18	2		*WINDSCREEN SEALANT	Necessary	268.00 FS	*241.20 FS
19	1		*PRIMER	Necessary	204.70 FS	*184.23 FS
20	1		*RIVET SILVER,REAR B 7 Pcs	Necessary	13.23 FS	*13.23 FS
21	1		*BUMPER REAR REINFORC	Repeated	708.48 FS	*- FS
22	10		*RIVET BLACK,BUMPER	Necessary	63.00 FS	*63.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **10,523.31** **7,408.62**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE TAILGATE,REAR BUMP REINFORCEMENT,END PANEL,LOWER BUMPER,BUMPER MOULDING,EMBLEMS,BRACKETS,CLIPS,ETC	New	3,300.00	1,100.00
2	TO BLEND AND SPRAY PAINT ON TAILGATE,REAR BUMPER,END PANEL,ETC	New	2,000.00	1,000.00
3	TO REPLACE REAR WINDSCREEN	New	550.00	550.00
4	TO INSTALL REAR WINDSCREEN SOLAR FILM	New	280.00	280.00
5	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	450.00	450.00
6	TO TRANSFER TAILGATE MECHANISM	New	250.00	250.00
Gross Labour Cost (\$)			6,830.00	3,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >