

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/HLA22002351/UQY3N2**Date:** 25/03/2022**REFERENCE**

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP315230
<b>Claimant Vehicle No :</b>	YQ897T	<b>Insured Vehicle No :</b>	SMQ6855S
Date of Loss:	24/09/2021	Nature of Claim:	TP
		Claim No:	MPC02853/JG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>YQ897T</b>	Engine No:	J08EWS10232
Make & Model:	HINO FG8JR1A 16 TON, 7.7 D (M)	Chassis No:	JHDFG8JR1XXX15334
Reg. Date:	23/04/2019 (Man. Year: 2018)	Odometer:	80431 km
Colour:	Silver		
Engine Capacity:	7685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	11R22.5	Rear Tyre Size:	11R22.5(D)
Front Left Side:	Akina 6 mm	Rear Left Side:	Sailun 6/6 mm
Front Right Side:	Akina 6 mm	Rear Right Side:	Sailun 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	650.00	0.00	650.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	550.00	380.00	170.00	30.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>1,200.00</b>	<b>380.00</b>	<b>820.00</b>	<b>68.33</b>

**INSPECTION**

Date of Assignment:	14/03/2022	
Date Inspected:	15/03/2022 Inspected At:	Liu's Brother Auto (HQ) No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	2.0 days	

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 Mar 2022)	
Parts:	N/A	HINO FG8JR1A 16 TON 7.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ897T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH LADDER PANEL	Repair	650.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					650.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS	New	250.00	200.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	300.00	180.00
<b>Gross Labour Cost (\$\$)</b>			<b>550.00</b>	<b>380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >