

Report No: 0032-22-TCA

23 May 2022

ACCIDENT VEHICLE SURVEY REPORT

Ho Hock Seng
11A Second Avenue
Singapore 266662

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SMA6170T	<i>Odometer:</i>	116575km
<i>Make & Model:</i>	Toyota Lexus RC F Coupe	<i>Colour:</i>	Black
<i>Chassis number:</i>	JTHHP5BC305001518	<i>Date of accident:</i>	11/03/2022
<i>Year of Regn.:</i>	24/04/2015	<i>Date inspected:</i>	15/03/2022
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	30/03/2022

STATIC CHECKS, where applicable:

<i>Steering :</i>	serviceable
<i>Footbrake :</i>	serviceable
<i>Handbrake :</i>	serviceable
<i>Paintwork :</i>	Good
<i>General condition :</i>	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
<i>Front:</i>	5mm/Michelin	5mm/Michelin	225/35ZR19
<i>Rear:</i>	5mm/Michelin	5mm/Michelin	225/35ZR19

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear and front portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
FRONT BONNET	1	repair	1,955.20	0.00
FRONT BONNET INSULATOR MAT CLIPS	9	necessay	31.50	31.50
FRONT BONNET MECHANISM LOCK	1	bent	168.50	168.50
FRONT BONNET RUBBER SEAL	1	reuse	32.00	0.00
FRONT BUMPER	1	squashed	1,073.50	1,073.50
FRONT BUMPER AIR GUIDE L/R	2	warped	226.00	226.00
FRONT BUMPER CHROME MOULDING	1	grazed/deform	356.80	356.80
FRONT BUMPER INNER SPONGE	1	fractured/defor	123.60	123.60
FRONT BUMPER INNER SPONGE BRACKET L/R	2	bent	201.40	201.40
FRONT BUMPER LAMP L/R	2	fractured	6,086.60	6,086.60
FRONT BUMPER PARKING SENSOR	2	shorted	1,079.60	1,079.60
FRONT BUMPER PARKING SENSOR HOLDER BRACKET	2	necessary	11.00	11.00
FRONT BUMPER REINFORCEMENT	1	bent	655.30	655.30
FRONT BUMPER SIDE RETAINER L/R	2	necessay	300.30	300.30
FRONT BUMPER TOW HOOK COVER	1	ripped	66.30	66.30
FRONT BUMPER UPPER RUBBER SEAL	1	deformed	56.70	56.70
FRONT GRILLE 'LOGO' EMBLEM	1	necessay	588.30	588.30
FRONT GRILLE (LOWER)	1	fractured/bent	1,514.48	1,514.48
FRONT GRILLE (UPPER)	1	fractured/bent	1,893.10	1,893.10
FRONT GRILLE CHROME MOULDING	1	grazed/bent	515.10	515.10
FRONT GRILLE UPPER COVERING	1	grazed/bent	377.30	377.30
FRONT HEADLAMP L/R	2	fractured	11,145.40	11,145.40
FRONT NUMBER PLATE BRACKET GARNISH	1	defomed	169.00	169.00
REAR BLIND SPOT SENSOR L/R	2	shorted	4,002.80	4,002.80
REAR BOOTLID	1	buckled	956.65	956.65
REAR BOOTLID 'L' LOGO EMBLEM	1	necessay	71.40	71.40
REAR BOOTLID 'LEXUS' EMBLEM	1	necessay	68.20	68.20
REAR BOOTLID 'RCF' EMBLEM	1	necessay	236.70	236.70
REAR BOOTLID HINGES L/R	2	repair	355.00	0.00
REAR BOOTLID INNER TRIM GARNISH	1	deformed	358.65	358.65
REAR BOOTLID MECHANISM LOCK	1	bent	548.65	548.65
REAR BOOTLID OUTER PROTECTOR	1	fractured	533.60	533.60
REAR BOOTLID REFLECTOR BACK GASKET SEAL L/R	2	necessay	78.80	78.80
REAR BOOTLID REFLECTOR L/R	2	fractured	1,378.90	1,378.90
REAR BOOTLID RUBBER GUIDE STOPPER L/R	2	deformed	38.00	38.00
REAR BOOTLID WEATHERSTRIP	1	deformed	261.69	261.69
REAR BUMPER	1	squashed	1,219.45	1,219.45
REAR BUMPER INNER SPONGE	1	fractured	161.55	161.55
REAR BUMPER LOWER LID GARNISH	1	fractured	461.70	461.70
REAR BUMPER REFLECTOR L/R	2	fractured	131.40	131.40
REAR BUMPER REINFORCEMENT	1	bent	984.15	984.15
REAR BUMPER REVERSE SENSOR	4	shorted	2,159.20	2,159.20

REAR BUMPER REVERSE SENSOR HOLDER	4	necessay	22.00	22.00
REAR BUMPER REVERSE SENSOR WIRE HARNESS	1	snapped	170.70	170.70
REAR BUMPER SIDE RETAINER L/R	2	necessay	329.70	329.70
REAR BUMPER TOW HOOK COVER L/R	2	reuse	56.60	0.00
REAR END PANEL	1	buckled	715.30	715.30
REAR END PANEL ANTENNA SENSOR	1	shorted	79.20	79.20
REAR END PANEL INNER TOP GARNISH	1	fractured	416.60	416.60
REAR SPARE TYRE TOP COVERING	1	deformed/fractured	453.90	453.90
REAR TAILLAMP L/R	2	fractured	1,730.10	1,730.10
REAR TAILLAMP LOWER BRACKET L/R	2	bent	130.40	130.40

Subtotal before discount S\$ 46,737.97 S\$ 44,339.17

Percentage discount 10% and 10% S\$ 4,673.80 S\$ 4,433.92

Sub-total 1 S\$ 42,064.17 S\$ 39,905.25

FRONT BONNET AIR VENT CLIPS	6	necessay	180.00	180.00
FRONT BUMPER CLIPS - SET	1	necessay	50.00	50.00
FRONT GRILLE UPPER COVERING CLIPS	8	necessay	480.00	480.00
FRONT NUMBER PLATE	1	bent	150.00	150.00
FRONT NUMBER PLATE HOLDER	1	bent	50.00	50.00
REAR BOOTLID HINGES COVER CLIPS L/R	6	necessay	120.00	120.00
REAR BOOTLID INNER TRIM GARNISH CLIPS - SET	1	necessay	50.00	50.00
REAR BOOTLID OUTER PROTECTOR	1	necessay	50.00	50.00
REAR BUMPER CLIPS - SET	1	necessay	50.00	50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessay	40.00	40.00
REAR END PANEL SEALANT	1	necessay	100.00	100.00
REAR NUMBER PLATE	1	reuse	150.00	0.00
REAR NUMBER PLATE HOLDER	1	reuse	50.00	0.00
REAR TAILLAMP CLIPS L/R - SET	2	necessay	40.00	40.00

Subtotal before discount S\$ 1,560.00 S\$ 1,360.00

Sub-total 2 S\$ 1,560.00 S\$ 1,360.00

Parts-total S\$ 43,624.17 S\$ 41,265.25

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)	60.00	60.00
To reset system after repair works	400.00	400.00
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	80.00	60.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	150.00	0.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1,500.00	1,250.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	1,300.00	750.00
To remove and reinstall exhaust pipe.	150.00	0.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,000.00	1,750.00
To apply anti-rust chemical on repaired and replaced panel.	100.00	90.00

Labour Total S\$ 5,740.00 S\$ 4,360.00

Parts & Labour Total S\$ 49,364.17 S\$ 45,625.25

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

**Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 38,800.00
and the recommended number of working days for the repairs is within 12 day(s).**



B J Loi (I Eng. MIMI, AIRTE)
Automotive Appraiser

