

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22002357/EVY3E2

Date: 17/06/2022

REFERENCE

Insured/Claimant: HIAP TAT HOLDING PTE. LTD. Policy No: DMCVSNA00061082101

Date of Loss: 10/03/2022

Nature of Claim: OD

Claim No: SNM22D201744/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE2110S**

Make & Model: MITSUBISHI FUSO, 12.0 D FV51SJD2DEA (M)

Engine No: OM457LA457972C0329537

Reg. Date: 25/08/2016 (Man. Year: 2016)

Chassis No: FV51SJA20040

Colour: White

Odometer: 0 km

Engine Capacity: 11967 cc

Market Value/New Car Price: S\$126,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5

Rear Tyre Size: 315/80 R22.5

Front Left Side: HIPERZEN 4 mm

Rear Left Side: HIPERZEN 4 mm

Front Right Side: HIPERZEN 4 mm

Rear Right Side: HIPERZEN 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	54,358.85	41,031.31	13,327.54	24.52
Miscellaneous Items	50.00	15.00	35.00	70.00
Labour	6,800.00	5,500.00	1,300.00	19.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	61,208.85	46,546.31	14,662.54	23.95
Approved Total (Overridden) (S\$)		37,200.00		
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	61,208.85	35,700.00	25,508.85	41.68
+ GST 7.00/7.00% (S\$)	4,284.62	2,499.00	1,785.62	41.68
Nett Amount (S\$)	65,493.47	38,199.00	27,294.47	41.68

INSPECTION

Date of Assignment: 14/03/2022 Present Location: Goldbell Engineering Pte Ltd (Tuas)

Date Inspected: 16/03/2022 Inspected At: Goldbell Engineering Pte Ltd (Tuas)

Estimated Period of Repair: 8.0 days 10 Tuas Ave 18

Singapore 638894

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Jun 2022)	
Parts:	N/A	mitsubishi fuso 12.0 D FV51SJD2DEA (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE2110S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WEATHERSTRIP,FR W/SHLD	Cut	365.22 F	*365.22 F
2	1		*GLASS,WINDSHIELD	Broken	1,652.45 F	*1,652.45 F
3	1		*PANEL,CAB,FR	Not Necessary	2,715.74 F	*- F
4	1		*W/STRIP,FR PANEL	Not Necessary	52.18 F	*- F
5	1		*STRAP,PULL DOWN	Not Necessary	47.54 F	*- F
6	1		*SPRING,FR PANEL	Not Necessary	251.88 F	*- F
7	1		*STAY ASSY,RAD GRILLE	Not Necessary	280.22 F	*- F
8	1		*BRACKET,CAB FR CORNER PANEL,LH	Not Necessary	95.46 F	*- F
9	1		*BRACKET,CAB FR CORNER PANEL,RH	Not Necessary	95.46 F	*- F
10	1		*GRILLE,FRONT UPR	Broken	288.90 F	*288.90 F
11	1		*GRILLE ASSY,FRONT	Broken	484.04 F	*484.04 F
12	1		*MARK,3-DIA	Necessary	57.87 F	*57.87 F
13	1		*EMBLEM,SUPER GREAT	Necessary	72.36 F	*72.36 F
14	1		*PILLAR ASSY RH	Repair	1,195.60 F	*- F
15	1		*PANEL,WINDSHIELD,UPR	Not Necessary	606.08 F	*- F
16	1		*PANEL,W/SHLD LOWER 96TC DO	Not Necessary	314.08 F	*- F
17	1		*GRIP,FR PANEL -LH	Not Necessary	123.50 F	*- F
18	1		*GRIP,FR PANEL -RH	Broken	123.50 F	*123.50 F
19	2		*GASKET,FR PANEL GRIP	Necessary	6.04 F	*6.04 F
20	2		*GASKET,FR PANEL GRIP	Necessary	12.80 F	*12.80 F
21	1		*CAP,FR PANEL GRIP	O/S Missing	14.72 F	*7.36 F
22	1		*COVER,FR GRIP	O/S Missing	23.32 F	*11.66 F
23	1		*MARK,FUSO	Necessary	90.09 F	*90.09 F
24	1		*ARM ASSY,WINDSHIELD WIPER,CTR	Bent	131.08 F	*131.08 F
25	1		*ARM ASSY,WINDSHIELD WIPER,LH	Bent	131.08 F	*131.08 F
26	1		*ARM ASSY,WINDSHIELD WIPER,RH	Bent	120.12 F	*120.12 F
27	3		*BLADE ASSY,WIPER	Cut	131.40 F	*131.40 F
28	1		*MOTOR,WINDSHIELD WIPER	Not Necessary	466.05 F	*- F
29	1		*GRILLE,DEFROSTER,FRONT	Not Necessary	124.86 F	*- F
30	1		*GRILLE,DEFROSTER,FRONT	Not Necessary	138.90 F	*- F
31	1		*PAD,INSTRUMENT PANEL	Broken	1,677.75 F	*1,677.75 F
32	1		*BEZEL,CTR	Not Necessary	213.18 F	*- F
33	1		*BEZEL,RH	Not Necessary	244.26 F	*- F
34	1		*BEZEL,LH	Not Necessary	448.06 F	*- F
35	1		*GARNISH,I/PNL,LH	Not Necessary	324.80 F	*- F
36	1		*BUMPER,FR	Not Necessary	1,570.67 F	*- F
Supplementary #1						
37	1		*CABIN HEAD	Dented	28,000.00 F	*24,000.00 F
Supplementary #2						
38	1		*BRACKET ASSY, CAB FR MOUNTING	Bent	1,500.00 F	*1,500.00 F
39	1		*FRAME ASSY, INST PANEL	Bent	844.64 F	*844.64 F
40	1		*FRAME ASSY, 5DIN	Bent	112.08 F	*112.08 F
41	1		*CONSOLE ASSY,FLOOR	Cracked	1,714.08 F	*1,714.08 F
42	1		*PANEL FLOOR CONSOLE, LH	Deformed	176.92 F	*176.92 F
43	1		*PANEL,C/LEVER	Cracked	283.94 F	*283.94 F
44	1		*LINK,W/SHLD WIPER	Bent	275.62 F	*275.62 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*METER COMBINATION	Cracked	3,340.78 F	*3,340.78 F
46	1		*PIPE,A/C COMPRESSOR SUCTION	Bent	208.66 F	*208.66 F
47	1		*COOLING UNIT,A/C	Cracked	1,490.79 F	*1,490.79 F
48	1		*BLOWER ASSY, HEATER	Cracked	409.95 F	*409.95 F
49	1		*HEATER ASSY	Cracked	1,310.13 F	*1,310.13 F
					Total Parts (\$\$)	54,358.85
						41,031.31

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT NUMBER PLATE (NOT NECESSARY)	35.00	0.00
2	1	IU BRACKET (NECESSARY)	15.00	15.00
Sub Total (\$\$)			50.00	15.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX FRONT WINDSCREEN	New	200.00	200.00
2	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN,ETC	New	3,600.00	3,500.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	New	200.00	150.00
4	TO REMOVE AND TO REMOVE AND REFIX FRONT DASHBOARD	New	700.00	600.00
5	TO REMOVE AND INSTALL MOBILEYE	New	400.00	0.00
6	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	New	1,700.00	1,050.00
Gross Labour Cost (\$\$)			6,800.00	5,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >