



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3876 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	XE2110S
Policy No:	DMCVSNA00061082101	Date of Loss:	10/03/2022
Vehicle Reg. No.:	XE2110S	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HIAP TAT HOLDING PTE. LTD.		
Driver:	PANDIAN ARUNKUMAR		

Make/Model:	mitsubishi fuso, 12.0 D FV51SJD2DEA (M)	Vehicle Reg. Date:	25/08/2016
Vehicle Colour:	WHITE	Chassis No:	FV51SJA20040
Engine No:	OM457LA457972C0329537		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		

Present Location: GOLDBELL ENGINEERING PTE LTD (TUAS)

COST OF CLAIMS

	Amount
Parts	14,691.26
Miscellaneous Items	50.00
Labour	6,800.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	21,541.26
+ GST 7.00% (S\$)	1,507.89
Nett Amount (S\$)	23,049.15

This claim is handled by: **CHONG KAI LING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 12 Mar 2022)**Parts:** N/A MITSUBISHI FUSO 12.0 D FV51SJD2DEA (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Goldbell Engineering Pte Ltd/XE2110S/12/03/2022 14:35**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*WEATHERSTRIP,FR W/SHLD / CM	0.00	0.00	*365.22 F
2	1		*GLASS,WINDSHIELD / OR	0.00	0.00	*1,652.45 F
3	1		*PANEL,CAB,FR / CR4	0.00	0.00	*2,715.74 F
4	1		*W/STRIP,FR PANEL / ?	0.00	0.00	*52.18 F
5	1		*STRAP,PULL DOWN / ?	0.00	0.00	*47.54 F
6	1		*SPRING,FR PANEL / ?	0.00	0.00	*251.88 F
7	1		*STAY ASSY,RAD GRILLE / ?	0.00	0.00	*280.22 F
8	1		*BRACKET,CAB FR CORNER PANEL,LH / ?	0.00	0.00	*95.46 F
9	1		*BRACKET,CAB FR CORNER PANEL,RH / ?	0.00	0.00	*95.46 F
10	1		*GRILLE,FRONT UPR / OR	0.00	0.00	*288.90 F
11	1		*GRILLE ASSY,FRONT / OR	0.00	0.00	*484.04 F
12	1		*MARK,3-DIA / NC	0.00	0.00	*57.87 F
13	1		*EMBLEM,SUPER GREAT / NC	0.00	0.00	*72.36 F
14	1		*PILLAR ASSY RH X R / NC	0.00	0.00	*1,195.60 F
15	1		*PANEL,WINDSHIELD,UPR / DO	0.00	0.00	*606.08 F
16	1		*PANEL,W/SHLD LOWER 96TC DO / DO	0.00	0.00	*314.08 F
17	1		*GRIP,FR PANEL -LH X	0.00	0.00	*123.50 F
18	1		*GRIP,FR PANEL -RH / OR	0.00	0.00	*123.50 F
19	2		*GASKET,FR PANEL GRIP / NC	0.00	0.00	*6.04 F
20	2		*GASKET,FR PANEL GRIP / NC	0.00	0.00	*12.80 F
21	2		*CAP,FR PANEL GRIP (RH) / MIS	0.00	0.00	*14.72 F
22	2		*COVER,FR GRIP (RH) / MIS	0.00	0.00	*23.32 F
23	1		*MARK,FUSO / NC	0.00	0.00	*90.09 F
24	1		*ARM ASSY,WINDSHIELD WIPER,CTR / BT	0.00	0.00	*131.08 F
25	1		*ARM ASSY,WINDSHIELD WIPER,LH / BT	0.00	0.00	*131.08 F
26	1		*ARM ASSY,WINDSHIELD WIPER,RH / BT	0.00	0.00	*120.12 F
27	3		*BLADE ASSY,WIPER / CM	0.00	0.00	*131.40 F
28	1		*MOTOR,WINDSHIELD WIPER / ?	0.00	0.00	*466.05 F
29	1		*GRILLE,DEFROSTER,FRONT / ?	0.00	0.00	*124.86 F
30	1		*GRILLE,DEFROSTER,FRONT / ?	0.00	0.00	*138.90 F
31	1		*PAD,INSTRUMENT PANEL / OR	0.00	0.00	*1,677.75 F
32	1		*BEZEL,CTR / ?	0.00	0.00	*213.18 F
33	1		*BEZEL,RH / ?	0.00	0.00	*244.26 F
34	1		*BEZEL,LH / ?	0.00	0.00	*448.06 F
35	1		*GARNISH,I/PNL,LH / ?	0.00	0.00	*324.80 F
36	1		*BUMPER,FR X	0.00	0.00	*1,570.67 F

F=Franchise part.

Total Parts (\$\$)**14,691.26**

Goldbell Engineering Pte Ltd/XE2110S/12/03/2022 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT NUMBER PLATE <i>X</i>	35.00
2	1	IU BRACKET <i>✓</i> <i>AK</i>	15.00
Sub Total (\$\$)			50.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE AND REFIX FRONT WINDSCREEN	New	200.00 <i>✓</i>
2	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC <i>600 X 5</i>	New <i>3500</i>	3,600.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	New <i>150</i>	200.00
4	TO REMOVE AND TO REMOVE AND REFIX FRONT DASHBOARD	New <i>600</i>	700.00
5	TO REMOVE AND INSTALL MOBILEYE	New <i>X</i>	400.00
6	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC <i>350 X 3</i>	New <i>1050</i>	1,700.00
Gross Labour Cost (\$\$)			6,800.00

Goldbell Engineering Pte Ltd/XE2110S/12/03/2022 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



Store CLKK)
16/3/22, 10:30 a

OP- M M
EXR H - ?
APD L/S
Ly AL Ty
8 dy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: