



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 9394D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	C&C LOGO (SN)	NECESSARY	40.00	40.00
1	SUNDRY (SN)	NECESSARY	20.00	20.00
1	FACE, RR BUMPER (SN)	BROKEN	890.00	890.00
1	REINFORCEMENT, RR BUMPER (SN)	NOT NECESSARY	234.00	-
1	BRACKET, RR BUMPER (SN)	BENT	17.00	17.00
1	BRKT, R/BMPR FACE SUPT, RH (SN)	NOT NECESSARY	27.00	-
1	BRKT, R/BMPR FACE SUPT, LH (SN)	NOT NECESSARY	27.00	-
1	COVER, RR FOG LAMP (SN)	NOT NECESSARY	44.00	-
1	PANEL, RR END (SN)	DENTED	261.00	261.00
1	PANEL ASSY, TAILGATE (SN)	DENTED	1,136.00	1,136.00
1	W/STRIP, TAILGATE OPENING (SN)	NOT NECESSARY	194.00	-
1	LATCH, TAILGATE (SN)	NOT NECESSARY	385.00	-
1	DAM, TAILGATE, LWR (SN)	NECESSARY	27.00	27.00
2	SPACER, TAILGATE (SN)	NECESSARY	6.00	6.00
4	FASTENER, WINDSHIELD (SN)	NECESSARY	24.00	24.00
1	MARK, ASX (SN)	NECESSARY	56.00	56.00
1	MARK, THREE-DIA (SN)	NECESSARY	70.00	70.00
1	ANT, KEYLESS OPERATION, RR (SN)	NOT NECESSARY	96.00	-
1	BUZZER, KEYLESS OPERATIO, RR (SN)	BROKEN	91.00	91.00
1	MUFFLER, EXHAUST MAIN (SN)	DENTED	637.00	637.00
1	PROT, UNDER RR FLOOR HEAT (SN)	NOT NECESSARY	93.00	-
1	PIPE, EXHAUST, CTR (SN)	NOT NECESSARY	1,263.00	-
1	HANGER, EXHAUST MUFFLER (SN)	NOT NECESSARY	24.00	-
2	STOPPER, WINDSHIELD GLASS (SN) (ADDITIONAL)	NECESSARY	6.00	6.00
			5,668.00	3,281.00
<u>LABOUR</u>				
RENEW REAR BUMPER, TAILGATE, REAR END PANEL.			2,560.00	1,280.00
REMOVE & INSTALL PARKING SENSOR.			100.00	80.00
REMOVE & INSTALL REAR COMPARTMENT TRIMS.			300.00	-
REMOVE & INSTALL TAILGATE GLASS.			300.00	300.00

Report Ref No. CS/AIS22002358/Ety3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT FOR REAR BUMPER, REAR END PANEL, TAILGATE.		2,200.00	1,100.00
	CHECK WIRING & ELECTRICAL SYSTEM.		30.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM.		280.00	280.00
	RENEW EXHAUST SYSTEM.		640.00	640.00
	SEALANT FOR ACCIDENT PORTION.		40.00	40.00
	SEALANT FOR TAILGATE GLASS.		80.00	80.00
	REPLACE REAR END PANEL. (ADDITIONAL)		1,280.00	1,280.00
	RESPRAY REAR END PANEL. (ADDITIONAL)		550.00	550.00
	SUPPLY ONE SET OF REVERSE SENSOR. (ADDITIONAL)		220.00	220.00
			8,580.00	5,880.00
	GRAND TOTAL		14,248.00	9,161.00
RECOMMENDED COST OF REPAIRS				9,161.00

Report Ref No. CS/AIS22002358/Ety3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.