

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002365/APA3Q2**Date:** 19/01/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100433348-06
Claimant Vehicle No :	SLV9372J	Insured Vehicle No :	SKV9845Z
Date of Loss:	15/03/2022	Nature of Claim:	TP
		Claim No:	0537705217SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV9372J	Engine No:	LEB6543026
Make & Model:	HONDA SHUTTLE, 1.5 G (A)	Chassis No:	GP71202456
Reg. Date:	23/01/2018 (Man. Year: 2017)	Odometer:	73559 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,694.48	5,730.12	4,964.36	46.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,179.00	1,929.00	1,250.00	39.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,873.48	7,659.12	6,214.36	44.79
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	13,873.48	6,100.00	7,773.48	56.03
+ GST 7.00/7.00% (S\$)	971.14	427.00	544.14	56.03
Nett Amount (S\$)	14,844.62	6,527.00	8,317.62	56.03
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,094.45		

INSPECTION

Date of Assignment:	15/03/2022	
Date Inspected:	15/03/2022	Inspected At: Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,209.20 FL	*1,050.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER O/S & N/S RETAINER	Necessary	182.00 FL	*75.00 FL
4	2		*REAR BUMPER O/S & N/S REFLECTOR	Not Necessary	162.60 FL	*- FL
5	1		*REAR BUMPER O/S & N/S REFLECTOR GARNISH	O/S Deformed	190.20 FL	*95.10 FL
6	1		*REAR TAIL-GATE	Distorted	1,309.00 FL	*1,195.00 FL
7	1		*REAR TAIL-GATE INNER TRIM	Cracked	391.60 FL	*285.00 FL
8	1		*REAR TAIL-GATE INNER TRIM CLIPS (16 PCS)	Necessary	144.00 FL	*30.00 FL
9	1		*REAR TAIL-GATE WEATHER STRIPS	Cut	189.00 FL	*189.00 FL
10	1		*REAR TAIL-GATE HONDA EMBLEM	Not Necessary	76.00 FL	*- FL
11	1		*REAR TAIL-GATE HYBRID GARNISH	Necessary	76.50 FL	*76.50 FL
12	1		*REAR TAIL-GATE SHUTTLE EMBLEM	Necessary	66.00 FL	*66.00 FL
13	1		*REAR TAIL-GATE MOULDING	Not Necessary	365.00 FL	*- FL
14	1		*REAR TAIL-GATE LOCK (UPPER)	Damaged	220.00 FL	*220.00 FL
15	1		*REAR TAIL-GATE LOCK (LOWER)	Not Necessary	102.00 FL	*- FL
16	1		*REAR TAIL-GATE HANDLE INNER	Deformed	54.60 FL	*54.60 FL
17	2		*REAR TAIL-GATE O/S & N/S REFLECTOR	Not Necessary	856.00 FL	*- FL
18	2		*REAR TAIL-GATE SHOCK ABSORBER	Not Necessary	468.60 FL	*- FL
19	2		*REAR TAIL-GATE O/S & N/S HINGES	Not Necessary	120.00 FL	*- FL
20	2		*REAR O/S & N/S FENDER INNER TRIM	Cracked	982.80 FL	*790.00 FL
21	1		*REAR END PANEL	Distorted	589.20 FL	*589.20 FL
22	1		*REAR END PANEL INNER TRIM	Deformed	212.40 FL	*212.40 FL
23	4		*REAR END PANEL INNER TRIM INNER TRIM CLIPS	Necessary	16.00 FS	*16.00 FS
24	1		*REAR O/S & N/S TAIL LAMP	O/S Cut	1,162.60 FL	*590.00 FL
25	1		*REAR O/S TAIL LAMP PANEL	O/S Dented	322.00 FL	*161.00 FL
26	1		*REAR BOOT FLOOR BOX	Deformed	320.40 FL	*320.40 FL
27	1		*REAR BOOT FLOOR BOX COVER	Not Necessary	86.50 FL	*- FL
28	1		*REAR BOOT FLOOR PANEL	Repair	1,620.00 FL	*- FL
29	1		*REAR BOOT FLOOR PANEL INSULATOR	Not Necessary	150.00 FS	*- FS
30	1		*REAR WINDSCREEN MOULDING	Necessary	160.00 FS	*160.00 FS
31	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
32	1		*REAR BUMPER TOW COVER	Deformed	80.00 FL	*45.00 FL
33	1		*REAR REG NO PLATE	Deformed	45.00 FS	*30.00 FS
34	1		*REAR REG NO PLATE BRACKET	Deformed	29.00 FS	*29.00 FS
35	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
36	1		*REAR SPARE WHEEL BOARD COVER	Not Necessary	310.20 FL	*- FL
37	2		*REAR O/S & N/S BUMPER SPONGE	Cracked	230.20 FL	*230.20 FL
38	1		*REAR O/S FENDER WHEEL GUARD	Torn	182.00 FL	*182.00 FL
39	1		*REAR END PANEL INNER TRIM STICKER	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,150.60	7,021.40
- List Item Discount on L Items 20.00/20.00% (\$)	2,456.12	1,291.28
Total Parts (\$)	10,694.48	5,730.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	1,600.00	800.00
2	TO SPRAY PAINTING	New	1,200.00	800.00
3	TO REMOVE & REFIR REAR REVERSE SENSOR CAMERA	New	50.00	50.00
4	TO REFIT AND REPLACE REAR TAIL GATE FITTINGS	New	60.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
6	TO CHECK WIRING	New	50.00	30.00
7	TO RE-SEAL ANTI-RUST	New	69.00	69.00
Gross Labour Cost (\$\$)			3,179.00	1,929.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >