

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22002369/TVCE2

Date: 16/06/2022

REFERENCE

Insured/Claimant: ONG SOO BOON Policy No: DMPCSNW00014152207

Date of Loss: 11/03/2022 Nature of Claim: OD Claim No: SNM22D201729/C01/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGV68G**
Make & Model: MERCEDES-BENZ E250, 2.0 SEDAN (A) Engine No: 27492030316125
Reg. Date: 27/01/2015 (Man. Year: 2014) Chassis No: WDD2120362B099792
Colour: White Odometer: 108189 km
Engine Capacity: 1991 cc
Market Value/New Car Price: S\$80,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/35 R18 Rear Tyre Size: 265/35 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------------------------|------------------|------------------|-----------------|--------------|
| Parts | 10,375.00 | 8,525.00 | 1,850.00 | 17.83 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,121.40 | 1,348.20 | -226.80 | -20.22 |
| Paintwork Labour | 766.29 | 1,064.64 | -298.35 | -38.93 |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 12,262.69 | 10,937.84 | 1,324.85 | 10.80 |
| Approved Total (Overridden) (S\$) | | 9,300.00 | | |
| - Excess (S\$) | 0.00 | 3,750.00 | -3,750.00 | |
| (S\$) | 12,262.69 | 5,550.00 | 6,712.69 | 54.74 |
| + GST 7.00/7.00% (S\$) | 858.39 | 388.50 | 469.89 | 54.74 |
| Nett Amount (S\$) | 13,121.08 | 5,938.50 | 7,182.58 | 54.74 |

INSPECTION

Date of Assignment: 15/03/2022 Present Location: Jin Auto Services Pte Ltd (Defu)
Date Inspected: 15/03/2022 Inspected At: Jin Auto Services Pte Ltd (Defu)
Estimated Period of Repair: 8.0 days Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 16 Jun 2022) |
| Parts: | 143 | MERCEDES-BENZ E250 2.0 SEDAN (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SGV68G) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|--------------------------------|-----|----------|-----------------------|-----------|------------------|-----------------|
| 1 | 1 | | *TOTAL PARTS | | 9,355.00 F | *7,505.00 F |
| 2 | 1 | | *SUNDRY | Necessary | 100.00 F | *100.00 F |
| <u>Supplementary #1</u> | | | | | | |
| 3 | 1 | | *R/R DOOR MODULE | Bent | 480.00 F | *480.00 F |
| 4 | 1 | | *R/R DOOR LOCK | Bent | 200.00 F | *200.00 F |
| 5 | 1 | | *R/R DOOR OUT HANDLE | Bent | 120.00 F | *120.00 F |
| 6 | 1 | | *R/R DOOR OUT SPEAKER | Distorted | 120.00 F | *120.00 F |
| Total Parts (S\$) | | | | | 10,375.00 | 8,525.00 |

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|----------------------------------------|----------|------------|----------|
| <u>Paintwork Labour</u> | | | | |
| 1 | TOTAL PAINT LABOUR CHARGE | New | 766.29 | 1,064.64 |
| <u>Labour Items</u> | | | | |
| 2 | TOTAL LABOUR CHARGE | New | 1,121.40 | 1,331.40 |
| 3 | RUSTPROOFING-RATE 4.0 WU X 42.00 SGD/H | New | - | 16.80 |
| Gross Labour Cost (\$\$) | | | 1,887.69 | 2,412.84 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >