

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22002371/AQCE2

Date: 16/09/2022

REFERENCE

Insured/Claimant: HAZLIE BIN RAHMAN Policy No: MPC22P00041700
Date of Loss: 10/03/2022 Nature of Claim: OD Claim No: DMPC2200098H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ8135K**
Make & Model: MERCEDES-BENZ E200, 1.8 (A) Engine No: 27195631106426
Reg. Date: 19/08/2008 (Man. Year: 2008) Chassis No: WDB2110412B368600
Colour: Black Odometer: 167776 km
Engine Capacity: 1796 cc
Market Value/New Car Price: S\$55,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R16 Rear Tyre Size: 225/55R16
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,526.80	9,324.70	3,202.10	25.56
Miscellaneous Items	85.00	85.00	0.00	0.00
Labour	1,225.00	760.00	465.00	37.96
Paintwork Labour	800.00	600.00	200.00	25.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,636.80	10,769.70	3,867.10	26.42
Approved Total (Overridden) (S\$)		8,600.00		
- Excess (S\$)	0.00	1,250.00	-1,250.00	
(S\$)	14,636.80	7,350.00	7,286.80	49.78
+ GST 7.00/7.00% (S\$)	1,024.58	514.50	510.08	49.78
Nett Amount (S\$)	15,661.38	7,864.50	7,796.88	49.78

INSPECTION

Date of Assignment: 15/03/2022 Present Location: Progressive Car Care Pte Ltd (HQ)
Date Inspected: 15/03/2022 Inspected At: Progressive Car Care Pte Ltd (HQ)
Estimated Period of Repair: 5.0 days Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Sep 2022)
Parts:	143	MERCEDES-BENZ E200 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ8135K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONNET (WCP)	Distorted	1,308.00 F	*1,308.00 F
2	2	NA	*BONNET HINGE - LH/RH (WCP)	Not Necessary	820.00 F	*- F
3	1	NA	*BONNET AIR VENT (WCP)	Not Necessary	134.00 F	*- F
4	1	NA	*BONNET INSULATOR (WCP)	Not Necessary	98.00 F	*- F
5	10	NA	*BONNET INSULATOR CLIPS (WCP)	Necessary	70.00 F	*70.00 F
6	1	NA	*BONNET LOCK - CENTRE (WCP)	Jammed	68.00 F	*68.00 F
7	1	NA	*BONNET LOCK CATCH - CENTRE (WCP)	Damaged	0.00 F	*- F
8	2	NA	*BONNET SIDE LOCK - TOP (WCP)	Jammed	92.00 F	*92.00 F
9	1	NA	*BONNET SIDE LOCK CATCH - TOP (WCP)	Damaged	0.00 F	*- F
10	1	NA	*BONNET LOGO (WCP)	Missing	60.00 F	*60.00 F
11	2	NA	*BONNET SPRING (WCP)	Damaged	92.00 F	*92.00 F
12	1	NA	*BONNET HANDLE CATCH (WCP)	Damaged	12.00 F	*12.00 F
13	1	NA	*FRONT BUMPER (WCP)	Deformed	875.00 F	*875.00 F
14	2	NA	*FRONT BUMPER SIDE RETAINER (WCP)	Damaged	112.00 F	*112.00 F
15	10	NA	*FRONT BUMPER CLIPS (WCP)	Necessary	50.00 F	*50.00 F
16	1	NA	*FRONT BUMPER TOW COVER (WCP)	Not Necessary	52.00 F	*- F
17	1	NA	*FRONT BUMPER LOWER GRILLE (WCP)	Not Necessary	28.00 F	*- F
18	2	NA	*FRONT BUMPER SIDE MOULDING (WCP)	Necessary	128.00 F	*128.00 F
19	1	NA	*FRONT BUMPER NO PLATE GARNISH (WCP)	Deformed	138.00 F	*138.00 F
20	2	NA	*FRONT BUMPER FOG LAMP - RH/LH (WCP)	Not Necessary	360.00 F	*- F
21	2	NA	*FRONT BUMPER FOGLAMP CHROME (WCP)	Not Necessary	110.00 F	*- F
22	1	NA	*FRONT BUMPER FOGLAMP COVER (WCP)	Not Necessary	18.00 F	*- F
23	1	NA	*AIR DUCT (WCP)	Not Necessary	61.00 F	*- F
24	1	NA	*FRONT BUMPER FOAM (WCP)	Not Necessary	43.00 F	*- F
25	1	NA	*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	415.00 F	*- F
26	2	NA	*HEADLAMP (WCP)	Cracked	1,104.00 F	*1,104.00 F
27	2	NA	*HEADLAMP PANEL (WCP)	Bent	172.00 F	*172.00 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1	NA	*FRONT FENDER (WCP)	N/s Dented	910.00 F	*455.00 F
29	2	NA	*FRONT FENDER COWLING (WCP)	Not Necessary	122.00 F	*- F
30	20	NA	*FRONT FENDER COWLING CLIPS (WCP)	Not Necessary	100.00 F	*- F
31	1	NA	*GRILLE W/LOGO (WCP)	Cracked	465.00 F	*465.00 F
32	1	NA	*SUPPORT PANEL (WCP)	Bent	96.00 F	*96.00 F
33	1	NA	*SUPPORT PANEL TOP GARNISH (WCP)	Not Necessary	63.00 F	*- F
34	1	NA	*CONDENSER (WCP)	Dented	730.00 F	*730.00 F
35	2	NA	*AIRCON SIDE GARNISH (NPA)	Not Necessary	0.00 F	*- F
36	1	NA	*AIRCON FAN MOTOR W/FAN BLADE (WCP)	Damaged	895.00 F	*895.00 F
37	1	NA	*RADIATOR (WCP)	Dented	1,555.00 F	*1,555.00 F
38	1	NA	*RADIATOR FAN MOTOR W/FAN BLADE & COWLING (NPA)	Not Necessary	0.00 F	*- F
39	1	NA	*RADIATOR TOP BEARING (WCP)	Not Necessary	18.00 F	*- F
40	2	NA	*RADIATOR TOP BEARING CLIPS (WCP)	Not Necessary	14.00 F	*- F

F=Franchise part.

Sub Total (S\$)	11,388.00	8,477.00
+ Margin on L,N Items 10.00/10.00% (S\$)	1,138.80	847.70
Total Parts (S\$)	12,526.80	9,324.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT NO PLATE W/CASING (BENT)	35.00	35.00
2	1	RADIATOR COOLANT (NECESSARY)	50.00	50.00
Sub Total (\$\$)			85.00	85.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	800.00	600.00
Labour Items				
2	TO KNOCK OUT DENTS; REMOVE; REPLACE ACCIDENT PARTS	New	1,000.00	600.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00	100.00
5	TO RESET CHECK LIGHT	New	75.00	30.00
Gross Labour Cost (\$\$)			2,025.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >