

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22002373/RPA3Q2**Date:** 17/02/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0006372_01
Claimant Vehicle No : SLL9539Z **Insured Vehicle No :** SHD2313T
 Date of Loss: 11/03/2022 Nature of Claim: TP Claim No: MFL2022D0001232

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL9539Z**
 Make & Model: TOYOTA VIOS, 1.5 E CVT (A) Engine No: 2NRX129795
 Reg. Date: 16/03/2017 (Man. Year: 2017) Chassis No: MHFB29F3802007389
 Colour: Grey Odometer: 267961 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R16 Rear Tyre Size: 195/50 R16
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	695.30	73.00	622.30	89.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,290.00	1,310.00	2,980.00	69.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,985.30	1,383.00	3,602.30	72.26
+ GST 7.00/7.00% (\$\$)	348.97	96.81	252.16	72.26
Nett Amount (\$\$)	5,334.27	1,479.81	3,854.46	72.26
+ Car Rental (4.0 x S\$52.30/day) (\$\$)		209.20		
Nett Liability (\$\$)		1,689.01		

INSPECTION

Date of Assignment: 15/03/2022
 Date Inspected: 11/04/2022 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
 2 Pandan Crescent
 Singapore 128462
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Sep 2022)
Parts:	143	TOYOTA VIOS 1.5 E CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL9539Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER RR BUMPER L	Repair	552.30 FS	*- FS
2	10		*PIECE RR BUMPER	Necessary	43.00 FS	*43.00 FS
3	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					695.30	73.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING & CONDUCT LEAK TEST	New	180.00	0.00
2	RESET ECU UPON COMPLETION OF REPAIR	New	180.00	0.00
3	REPL ACC AFF AREA STRAIGHTEN & PANEL BEAT ACC AFF AREA	New	2,160.00	720.00
4	RESPRAY ACC AFF AREA	New	1,770.00	590.00
Gross Labour Cost (\$\$)			4,290.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >