



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMW 6310R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BROKEN	682.90	682.90
1	FRONT BUMPER SIDE RETAINER (LHS)	BROKEN	65.00	65.00
10	FRONT BUMPER CLIPS @\$4.00	NECESSARY	40.00	30.00
1	FRONT BUMPER FOGLAMP COVER (LHS)	NOT NECESSARY	125.20	-
1	FRONT BUMPER FOGLAMP (LHS)	NOT NECESSARY	682.50	-
1	FRONT FENDER (LHS)	TO REPAIR SEE LABOUR	495.50	-
1	FRONT FENDER SPLASH SHIELD (LHS)	NOT NECESSARY	172.00	-
10	FRONT FENDER SPLASH SHIELD CLIPS @\$4.00	NOT NECESSARY	40.00	-
1	FRONT HEADLAMP (LHS)	* CHECK	2,250.30	-
1	FRONT WHEEL HUP CAP (LHS)	CUT	346.40	346.40
	LESS 20% DISCOUNT		-979.96	-224.86
			3,919.84	899.44
	<u>LABOUR</u>			
	TO REMOVE & REFOCUS FRONT HEADLAMP.		100.00	30.00
	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.		80.00	30.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TO KNOCKING & PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER (LHS).		600.00	250.00
	TO PUTTY & SPRAY PAINT ALL THE AFFECTED AREAS.		600.00	400.00
			1,530.00	770.00
GRAND TOTAL			5,449.84	1,669.44
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,800.24 NETT)				1,669.44

Report Ref No. CS/INC22002376/Evy3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.