

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002377/GVY3M4**Date:** 01/08/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00012282101
Claimant Vehicle No :	SLN5370H	Insured Vehicle No :	SLL7149D
Date of Loss:	06/03/2022	Nature of Claim:	TP
		Claim No:	SNM22D201666/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN5370H	Engine No:	L15B4532474
Make & Model:	HONDA HR-V, 1.5 (A)	Chassis No:	JHMRU1810GX202474
Reg. Date:	08/05/2017 (Man. Year: 2017)	Odometer:	93656 km
Colour:	Green		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,770.16	846.72	923.44	52.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	800.00	360.00	31.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,930.16	1,646.72	1,283.44	43.80
+ GST 7.00/7.00% (\$\$)	205.11	115.27	89.84	43.80
Nett Amount (\$\$)	3,135.27	1,761.99	1,373.28	43.80

INSPECTION

Date of Assignment:	18/03/2022	
Date Inspected:	15/03/2022	Inspected At: 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY, SINGAPORE 575722 REPAIRER: VIN'S MOTOR PTE LTD
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2022)
Parts:	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN5370H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Repair	950.20 FL	*- FL
2	1		*FRONT RH DOOR OUTER MOULDING	Not Necessary	60.20 FL	*- FL
3	1		*FRONT RH DOOR FRAME PILLAR STICKER	Not Necessary	78.60 FL	*- FL
4	1		*REAR RH DOOR	Buckled	930.60 FL	*930.60 FL
5	1		*REAR RH DOOR OUTER MOULDING	Not Necessary	65.30 FL	*- FL
6	1		*REAR RH DOOR FRAME PILLAR STICKER	Necessary	78.60 FL	*78.60 FL
7	1		*REAR RH DOOR VERTICAL RUBBER	Cut	49.20 FL	*49.20 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	2,212.70	1,058.40
- List Item Discount on L Items 20.00/20.00% (\$)	442.54	211.68
Total Parts (\$)	1,770.16	846.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR RH DAMAGES	New	480.00	400.00
2	TO SPRAY PAINTING	New	680.00	400.00
Gross Labour Cost (S\$)			1,160.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >