



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 9803R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET	BUCKLED	890.00	890.00
1	BONNET HINGE RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	BONNET HINGE RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	INSULATOR	SERVICEABLE	285.00	-
6	INSULATOR CLIP	NOT NECESSARY	36.00	-
1	FRT NUMBER PLATE BASE	DENTED	115.00	115.00
1	FRT BUMPER	BUCKLED / CRACKED	920.00	920.00
1	FRT BUMPER LOWER CENTRE GRILLE	DENTED / CUT	460.00	460.00
1	FRT BUMPER SPONGE	SERVICEABLE	155.00	-
1	FRT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	440.00	-
1	FRT BUMPER SIDE RETAINER RH	DISTORTED	65.00	65.00
1	FRT BUMPER SIDE RETAINER LH	DISTORTED	65.00	65.00
1	RADIATOR GRILLE	DISTORTED	380.00	380.00
1	RADIATOR GRILLE LOGO	DENTED	155.00	155.00
1	HEADLAMP RH	MTG BROKEN	680.00	680.00
1	HEADLAMP LH	MTG BROKEN	680.00	680.00
1	A/C CONDENSER FRT TOP DUCT	SERVICEABLE	230.00	-
1	A/CON CONDENSER	BENT	820.00	820.00
1	RADIATOR	PUNCTURE	550.00	550.00
1	COOLANT	NECESSARY	38.00	38.00
1	RADIATOR FAN MOTOR	CRACKED	910.00	910.00
1	RADIATOR FAN MOTOR BLADE (NPA)	NOT NECESSARY	-	-
1	A/CON FAN MOTOR (NPA)	NOT NECESSARY	-	-
1	A/CON FAN MOTOR BLADE (NPA)	NOT NECESSARY	-	-
1	RADIATOR FAN COWLING (NPA)	NOT NECESSARY	-	-
1	RADIATOR SPARE TANK	SERVICEABLE	195.00	-
1	FRT SUPPORT PANEL TOP	BUCKLED	290.00	290.00
1	FRT HEADLAMP PANEL RH	TO REPAIR SEE LABOUR	230.00	-

Report Ref No. CS/FCI22002384/Kty3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT HEADLAMP PANEL LH	TO REPAIR SEE LABOUR	230.00	-
1	FRT LH FENDER	BUCKLED	450.00	450.00
1	BONNET LOCK (ADDITIONAL)	DISTORTED	122.00	122.00
	LESS 10% DISCOUNT		-939.10	-759.00
			8,451.90	6,831.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRT NO PLATE W/CASE / SILVER / EMBOSS (SN)	BENT	45.00	45.00
1	BONNET PUB STICKER (SN) (ADDITIONAL)	NECESSARY	150.00	150.00
			195.00	195.00
	<b><u>LABOUR</u></b>			
	TO CUT, WELD FRONT PANEL, JACK, STRAIGHTEN FRONT AFFECTED AREAS, REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF BONNET HINGE RH, BONNET HINGE LH, FRT BUMPER REINFORCEMENT, FRT HEADLAMP PANEL RH AND FRT HEADLAMP PANEL LH.		1,200.00	600.00
	PUTTY, RESPRAY BONNET, FRT BUMPER, BOTH FENDERS AND AFFECTED AREAS.		1,000.00	900.00
	TO REMOVE RADIATOR AND CONDENSER TO ASSIST REPAIR AND REPLACE. }		180.00	120.00
	TOP UP AIRCON GAS. }		80.00	-
	CHECK LIGHTING AND WIRING.		50.00	20.00
			2,510.00	1,640.00
<b>GRAND TOTAL</b>			<b>11,156.90</b>	<b>8,666.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>8,666.00</b>
<b>LESS EXCESS</b>			<b>-500.00</b>
<b>NETT LIABILITY</b>			<b>8,166.00</b>

Report Ref No. CS/FCI22002384/Kty3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.