

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM22002387/Aea3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	19/08/2022	
	ATTN:GARNET			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SH 8352P	Veh. Inspected		SH 4880H	
	Policy No.	P2465679	Coverage (\$)		0.00	
	Claim No.	S2M03VJX	Excess (\$)		0.00	
	Assign From		Assign Date		15/03/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA AXIO	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	NZE1617065470	Colour		BLACK	
	Odometer	938559 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/65 R15	HABILEAD		6 mm	
	L/H Front Tyre	185/65 R15	HABILEAD		6 mm	
	R/H Rear Tyre	185/65 R15	HABILEAD		6 mm	
	L/H Rear Tyre	185/65 R15	HABILEAD		6 mm	
4.	. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	11/03/2022	Inspection Dat	е	21/03/2022	
	Survey held at HUA MENG SPRAY PAINTING WORKSHOP					
		1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		4 Worki	ng Days	