

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22002394/GQY3Q2**Date:** 19/09/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00127202100		
<b>Claimant Vehicle No :</b>	SLL5927M	<b>Insured Vehicle No :</b>	GBJ9858G		
Date of Loss:	12/03/2022	Nature of Claim:	TP	Claim No:	SNM22D201778/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLL5927M</b>		Engine No:	PE10439851
Make & Model:	MAZDA 5 WAGON, 2.0 EU6 (A)		Chassis No:	JM6CW1071G0125180
Reg. Date:	28/02/2017 (Man. Year: 2016)		Odometer:	75028 km
Colour:	Silver			
Engine Capacity:	1998 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Yes

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,854.00	5,821.92	2,032.08	25.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,400.00	440.00	23.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,694.00</b>	<b>7,221.92</b>	<b>2,472.08</b>	<b>25.50</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,750.00</b>		
<b>(S\$)</b>	9,694.00	5,750.00	3,944.00	40.68
<b>+ GST 7.00/7.00% (S\$)</b>	678.58	402.50	276.08	40.68
<b>Nett Amount (S\$)</b>	<b>10,372.58</b>	<b>6,152.50</b>	<b>4,220.08</b>	<b>40.68</b>

INSPECTION

Date of Assignment:	15/03/2022	
Date Inspected:	22/03/2022	Inspected At: Vin's Auto Pte Ltd (Vin's Auto) Sin Ming AutoCity,, 160 Sin Ming Drive #03-03 Singapore 575722
Estimated Period of Repair:	5.0 days	

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 15 Sep 2022)	
<b>Parts:</b>	N/A	MAZDA 5 WAGON 2.0 EU6 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLL5927M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Buckled	1,700.00 FL	*1,700.00 FL
2	1		*REAR TAILGATE GLASS MOULDING	Necessary	61.00 FL	*61.00 FL
3	1		*REAR TAILGATE OUTER GARNISH	Cracked	485.00 FL	*175.00 FL
4	1		*REAR TAILGATE EMBLEM	Necessary	45.00 FL	*45.00 FL
5	1		*REAR TAILGATE MAZDA EMBLEM	Necessary	46.00 FL	*46.00 FL
6	1		*REAR TAILGATE 5 EMBLEM	Necessary	37.00 FL	*37.00 FL
7	1		*REAR TAILGATE SKYACTIV TECHNOLOGY EMBLEM	Necessary	80.00 FL	*48.00 FL
8	1		*REAR TAILGATE RH REFLECTOR	Cut	389.00 FL	*356.00 FL
9	1		*REAR TAILGATE LH REFLECTOR	Cut	389.00 FL	*356.00 FL
10	1		*REAR TAILGATE INNER TRIMBOARD	Broken	432.00 FL	*432.00 FL
11	1		*REAR TAILGATE LOCK	Cut	257.00 FL	*257.00 FL
12	1		*REAR TAILGATE RUBBER	Twisted	178.00 FL	*178.00 FL
13	1		*REAR RH TAILLAMP	Cracked	602.00 FL	*602.00 FL
14	1		*REAR LH TAILLAMP	Cracked	602.00 FL	*602.00 FL
15	1		*REAR BUMPER	Deformed	962.00 FL	*915.40 FL
16	1		*REAR BUMPER RH REFLECTOR	Not Necessary	53.00 FL	*- FL
17	1		*REAR BUMPER LH REFLECTOR	Not Necessary	53.00 FL	*- FL
18	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	48.00 FL	*- FL
19	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	48.00 FL	*- FL
20	1		*REAR BUMPER ANTENNA SENSOR	Not Necessary	168.00 FL	*- FL
21	1		*REAR BUMPER BUZZIE SENSOR	Not Necessary	102.00 FL	*- FL
22	1		*REAR BUMPER CLIPS	Necessary	4.50 FL	*4.50 FL
23	1		*REAR END PANEL	Repair	576.00 FL	*- FL
24	1		*REAR END PANEL TOP TRIM	Deformed	81.00 FL	*81.00 FL
25	1		*REAR TOOL BOX	Cut	1,110.00 FL	*385.00 FL
26	1		*REAR TOOL BOX TOP COVER	Cut	178.00 FL	*178.00 FL
27	1		*REAR TAILGATE REVERSE CAMERA	Cracked	380.00 FS	*250.00 FS
28	1		*REAR BUMPER PARKING SENSOR	Damaged	280.00 FS	*200.00 FS
29	1		*REAR WINDSCREEN GUM	Necessary	80.00 FS	*40.00 FS
30	1		*REAR BUMPER REINFORCEMENT	Bent	156.00 FL	*156.00 FL
31	1		*REAR NO PLATE	Cut	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,622.50</b>	<b>7,144.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,768.50	1,322.98
<b>Total Parts (\$\$)</b>	<b>7,854.00</b>	<b>5,821.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIX REAR WINDSCREEN	New	180.00	120.00
2	TO REPAIR DAMAGES	New	780.00	580.00
3	TO SPRAY PAINTING	New	880.00	700.00
			<b>Gross Labour Cost (\$)</b>	<b>1,840.00</b>
				<b>1,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >