

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	CS/INC22002395/Ety3s2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	23/05/2022	
	ATTN: CHARLOTT	E		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SGW 6139R	Veh. Inspected		SLB 4324L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1159905-002	Excess (\$)		0.00	
	Assign From	Theresa Vimala	Assign Date		15/03/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA AXIO	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	NRE1610011213	Colour		GOLD	
	Odometer	196518 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	DUNLOP		4 mm	
	L/H Front Tyre	185/60 R15	DUNLOP		4 mm	
	R/H Rear Tyre	185/60 R15	DUNLOP		4 mm	
	L/H Rear Tyre	185/60 R15	DUNLOP		4 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.		General Information				
	Accident Date	26/01/2022	Inspect Date / 1	Гіте	15/03/2022 (12:00 PM)	
	Survey held at	AUTO WHEELS MOTORWORKS				
	,	NO 1 BUKIT BATOK CRESCENT #02-40 WCEGA PLAZA SINGAPORE 658064				
5a.	·	Remarks				
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				