



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 5002X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR RH	DENTED	1,358.40	1,049.00
1	REAR DOOR STICKER RH (SET)	NECESSARY	85.60	85.60
1	REAR DOOR HINGE RH (UPPER)	NOT NECESSARY	45.50	-
1	REAR DOOR HINGE RH (LOWER)	NOT NECESSARY	45.50	-
1	REAR DOOR CHECKER RH	NOT NECESSARY	64.20	-
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER PROTECTOR STICKER RH	NECESSARY	64.20	64.20
1	REAR BUMPER	CRUSHED	1,124.50	1,124.50
10	REAR BUMPER CLIPS	NECESSARY	50.00	30.00
1	REAR BUMPER SIDE BRACKET RH	BROKEN	64.30	64.30
	LESS 20% DISCOUNT		-580.44	-483.52
			2,321.76	1,934.08
	<u>LABOUR</u>			
	LABOUR TO FACILITATE REPAIR.INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		800.00	600.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRING.		35.00	30.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		700.00	600.00
	SPRAY RUST PROOF ON AFFECTED AREA.		40.00	30.00
			1,575.00	1,260.00
	GRAND TOTAL		3,896.76	3,194.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,550.00

Report Ref No. CS/INC22002397/Ety3n2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.