

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 1693J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR SIDE LAMP RH	NOT NECESSARY	67.20	-
1	FRONT BUMPER	DEFORMED	380.40	380.40
1	CABIN LEVER BRACKET	CRACKED	780.40	780.40
1	FRONT GRILLE	MISSING	487.30	487.30
1	FRONT WING MIRROR COVER RH	CRACKED	141.20	141.20
1	FRONT HEADLAMP PANEL COVER RH	BENT	215.40	215.40
1	FRONT HEADLAMP RH	BROKEN	489.10	489.10
1	FRONT PANEL	BENT	984.80	984.80
1	FRONT WINDSCREEN GLASS LOWER RUBBER MOULDING	DISTORTED	152.40	152.40
1	FRONT WINDSCREEN GLASS	CRACKED	587.40	587.40
	LESS 10% DISCOUNT		-428.56	-
	LESS 30% DISCOUNT		-	-1,265.52
			3,857.04	2,952.88
	SPECIAL NETT ITEMS			
1	FRONT NO PLATE (SN)	SCRATCHED	25.00	25.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	50.00	30.00
			75.00	55.00
	<u>LABOUR</u>			
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND RESETTING HEADLAMP FOCUSSING (TO FR).		100.00	30.00
	TO REMOVE,CHANGE FRONT WINDSCREEN.		150.00	120.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	600.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		1,000.00	600.00
			2,250.00	1,350.00
	GRAND TOTAL		6,182.04	4,357.88

Report Ref No. CS/INC22002398/Rty3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,500.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. CS/INC22002398/Rty3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser