



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 9750P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	480.00	-
1	FRONT BUMPER RETAINER LH	SERVICEABLE	220.00	-
1	FRONT FENDER LH	BENT	385.00	385.00
1	FRONT FENDER UNDERSHIELD LH	SERVICEABLE	282.00	-
1	HEADLAMP LH	CUT	524.00	495.70
	LESS 25% DISCOUNT		-472.75	-220.18
			1,418.25	660.52
	<u>SPECIAL NETT ITEMS</u>			
10	FRONT BUMPER CLIPS (SN)	NECESSARY	35.00	35.00
10	FRONT FENDER UNDERSHIELD CLIPS (SN)	NOT NECESSARY	35.00	-
1	FRONT RIM LH (DENTED)(SN)	NOT CONSISTENT WITH THE IMPACT	500.00	-
			570.00	35.00
	<u>LABOUR</u>			
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		800.00	360.00
	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		800.00	400.00
	TO DO COMPUTER WHEEL ALIGNMENT.		80.00	60.00
	TO DO ANTI RUST.		90.00	30.00
	CHECK WIRING SYSTEM,REPLACE FOCUS HEADLAMPS.		120.00	20.00
			1,890.00	870.00
	GRAND TOTAL		3,878.25	1,565.52
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,250.00

Report Ref No. CS/INC22002403/Kvy3n2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.