## KK

Kamaliah KAMIS (SPF) < Kamaliah\_KAMIS @ spf.gov.sg>
Tue 15/3/2022 12:14 PM

assistance to expedite on it.

May I seek your assistance to perform a detailed mechanical inspection of the following <u>18</u> <u>cases</u> in the table below. The ones in <u>red are deemed to urgent</u> hence requesting for your kind

SN	Case IAFP-IB-	Brief Facts	Vehicles to	IO In-Charge:
314	20211028	bilei racts	be	io ili-cilarge.
	20211020		inspected:	
	IP No.		mspected.	
1-2	TP/IP/55291/2021	On 20 November 2021 at about 2223 hrs, (B1) <b>SHA8836C</b> was travelling along Yishun Central towards Yishun Avenue 5 on lane 2 of a 2 lane road, has stationary at the pedestrian crossing before KTPH entrance, due to red light. Upon traffic light change to green light signal, B1 proceed to move off and went straight for a short distance before making a left turn into KTPH. While turning left, B2 (Bicycle) suddenly appeared infront of B1 and hence unable to stop in time, B1's front left portion collided onto B2. Due to the RTA, B2 was pushed to KTPH, A&E by nurses' station nearby at KTPH in a conscious state. B2 sustained forehead cut, abrasion on his limbs and arms. B2 will be admitted in a normal ward, for monitoring and further scan. It was informed that B2 will be warded for long due to spinal injuries. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	SHA8836C - Driver (Potential Defendant)  Bicycle - Pedal Cyclist (Victim)	Ng Beifeng

3	TP/IP/02286/2022	On 28 January 2022 (Thursday)	SKH4566K -	Sophian
	,, 52200, 2022	at about 1.57 a.m., the driver of	Driver	oopman
		motorcar SKH4566K (A1) were	_	
		involved with in an accident	(Victim)	
		along Bukit Batok Road x Bukit		
		Batok West Avenue 7. After		
		which the car was towed back for		
		safe custody. While the towing		
		was on the way pound, the		
		SKH4566K caught fire. I would		
		the car to be inspected to		
		confirm that the car was caught		
		fire not due to our towing crew		
		that was towing the car. A		
		detailed mechanical inspection		
		is required to eliminate any		
		mechanical fault or any possible		
		defence and to rule out foul		
		play.		
		. ,		

4	TP/IP/56467/2021	On 28/11/2021 at about 0348hrs, the	SJU5978S -	Yeo Kia Huat
		driver of motorcar, SJU5978S was	Driver	
		travelling on the single lane road along the	(Potential	
		slip road of Eunos Link into Ubi Avenue 2	Defendant)	
		when the front right tyre rim of his		
		motorcar broke off and caused him to lose		
		control and skidded. Driver of SJU5978S		
		claimed that the crankshaft of his motorcar		
		broke prior to the accident. A detailed		
		mechanical inspection is required to		
		eliminate any mechanical fault or any		
		possible defence and to rule out foul play.		

7	TP/IP/03912/2022	On 19 February 2022, a motorcar was	JNY5964 -	Syakir
		travelling on lane 4 of 5-lane road and	Driver	
		Malaysian Trailer was travelling on lane 3	(Potential	
		of 5-lane road. While travelling just abreast	Defendant)	
		to each other, both parties confirmed to		
		hear a loud bang and moments later, the		
		driver to the motorcar felt and impact from		
		the right. Upon stopping for checks, one of		
		the rims from the Malaysian Trailer was		
		found dislodged from the axel and had hit		
		onto the right portion of the motorcar. A		
		detailed mechanical inspection is required		
		to eliminate any mechanical fault or any		
		possible defence and to rule out foul play.		

9	TP/IP/02918/2022	On 7 February 2022 at about 8.12 a.m.,	PA7894X -	Siti Norhafidah
		motor van PA7894X was involved in an	Driver	
		accident with government property. As a	(Potential	
		result of the accident, 8 passengers were	Defendant)	
		conveyed to different hospitals. According		
		to the driver (B1), she was travelling on		
		lane 1 of 2-lane road of slip road from CTE		
		(SLE) into Seletar West Link. While		
		negotiating a downslope left bend at speed		
		of about 50 km/h, B1 realized that the van		
		was going faster. B1 then braked and		
		managed to slow down. However, B1 still		
		lost control of the van causing it to veer to		
		the right, mounted the kerb and toppled to		
		its right side. B1 claimed there is no		
		mechanical fault to the van. A detailed		
		mechanical inspection is required to		
		eliminate any mechanical fault or any		
		possible defence and to rule out foul play.		

10	TP/IP/04581/2022	On 02 March 2022 sometime before 6.38	GBA3054A -	Adrian
-		a.m., the Involved Party was driving his	Driver	
11		lorry along Sembawang Road on lane 1 of 2	(Potential	
		lanes road when he collided onto the	Defendant)	
		Cyclist, who was cycling his bicycle across		
		the road at the pedestrian crossing. Cyclist	Bicycle -	
		was conveyed to CGH and pronounced	Pedal	
		dead on the same day with multiple	Cyclist	
		injuries at 7.34a.m. A detailed mechanical	(Deceased)	
		inspection is required to eliminate any		
		mechanical fault or any possible defence		
		and to rule out foul play.		

12	TP/IP/00600/2022	On 9 January 2022 (Sunday) at about 12.06	SJD5744P -	Afiq
		a.m., the driver of motor car SJD5744P (B1)	Driver	
		was travelling along the slip road of Pasir	(Potential	
		Ris Drive 8 into Pasir Ris Drive 1 towards	Defendant)	
		Pasir Ris Drive 12 and she claimed the		
		brakes were not working and caused her		
		lost control of the vehicle and collided onto		
		the green railings on the center divider		
		along Pasir Ris Drive 1. A detailed		
		mechanical inspection is required to		
		eliminate any mechanical fault or any		
		possible defence and to rule out foul play.		

TD/ID/04EE9/2022	On 26 Fohruary 2022 at about 4.21 n.m.	CN/D11271	Shives
17/17/04336/2022	•		Shivas
	G	_	
	the LTA sky camera and the in-vehicle	(Deceased)	
	camera from the Deceased's motorcar, it		
	revealed that the Deceased's motorcar was		
	travelling along KPE (TPE), slip road into		
	Lorong Halus on lane 3 of the 3-lane road		
	when it slowly veered to the right into lane		
	2, lane 1 and subsequently the right		
	portion of the Deceased's motorcar grazed		
	onto the centre divider wall. The		
	Deceased's motorcar then continued to		
	graze the wall, grazed onto the centre		
	guard railings, and mounted the curb side		
	on the centre guard railings before coming		
	to a stop. A detailed mechanical inspection		
	is required to eliminate any mechanical		
	fault or any possible defence and to rule		
	out foul play.		
	. ,		
	TP/IP/04558/2022	based on the video footages retrieved from the LTA sky camera and the in-vehicle camera from the Deceased's motorcar, it revealed that the Deceased's motorcar was travelling along KPE (TPE), slip road into Lorong Halus on lane 3 of the 3-lane road when it slowly veered to the right into lane 2, lane 1 and subsequently the right portion of the Deceased's motorcar grazed onto the centre divider wall. The Deceased's motorcar then continued to graze the wall, grazed onto the centre guard railings, and mounted the curb side on the centre guard railings before coming to a stop. A detailed mechanical inspection is required to eliminate any mechanical	based on the video footages retrieved from the LTA sky camera and the in-vehicle camera from the Deceased's motorcar, it revealed that the Deceased's motorcar was travelling along KPE (TPE), slip road into Lorong Halus on lane 3 of the 3-lane road when it slowly veered to the right into lane 2, lane 1 and subsequently the right portion of the Deceased's motorcar grazed onto the centre divider wall. The Deceased's motorcar then continued to graze the wall, grazed onto the centre guard railings, and mounted the curb side on the centre guard railings before coming to a stop. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule

15	TP/IP/05098/2021	On 4 March 2022 sometime before 2.41	SJQ1937H -	Kamaliah
-		p.m., based on the video footage retrieved	Driver	
16		from the Accused's motorcar, it revealed	(Potential	
		that the Accused was travelling straight	Defendant)	
		along PIE (Tuas), 36 km on lane 5 of the 5-		
		lane road when he slowly made a left lane	FBN2023Z -	
		changed to the road shoulder. While	Rider	
		moving slowly along the road shoulder, the	(Deceased)	
		Accused's motorcar slowed down and		
		came to a stop. At this juncture, the		
		Deceased's motorcycle was travelling		
		straight on lane 5 and was approaching the		
		Accused's motorcar from the rear.		
		Subsequently, the front portion of the		
		Deceased's motorcycle collided onto the		
		rear right portion of the Accused's		
		stationary motorcar. Due to the collision,		
		the Deceased's motorcycle skidded		
		forward while the Deceased and the Victim		
		flung forward, not far from the Deceased's		
		motorcycle. A detailed mechanical		
		inspection is required to eliminate any		
		mechanical fault or any possible defence		
		and to rule out foul play.		

17	TP/IP/05094/2022	On 4 March 2021 sometime before 10.30	XE507U-	Kamaliah
-		a.m., based on the video footage retrieved	Driver	
18		from both vehicles, it revealed that the	(Involved	
		Involved Party's tipper truck was travelling	Party)	
		straight along Kranji Road towards End on		
		lane 1 of the 3-lane road. At this juncture,	GBD9912P -	
		the Accused's lorry was travelling straight	Driver	
		on lane 2, abreast to the Involved Party's	(Potential	
		tipper truck. Out of a sudden, the	Defendant)	
		Accused's lorry slowly moved towards the		
		Involved Party's tipper truck and		
		encroached into the travel path of the		
		Involved Party's tipper truck. As such, the		
		right frontal portion of the Accused's lorry		
		collided onto the left front portion of the		
		Involved Party's tipper truck. A detailed		
		mechanical inspection is required to		
		eliminate any mechanical fault or any		
		possible defence and to rule out foul play.		