

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002411/BVY3E2**Date:** 15/02/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00009252101

**Claimant Vehicle
No :** SNE1648H**Insured Vehicle
No :** SLQ5980G

Date of Loss: 10/03/2022

Nature of Claim: TP

Claim
No: SNM22D201706/C02/IRENEDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNE1648H**

Make & Model: AUDI S5, 3.0 CABRIOLET (A)

Engine No: CAK014299

Reg. Date: 16/11/2010 (Man. Year: 2010)

Chassis No: WAUZZZ8T9BA023609

Colour: Blue

Odometer: 147739 km

Engine Capacity: 2995 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/30 R20

Rear Tyre Size: 275/30 R20

Front Left Side: Pirelli 4 mm

Rear Left Side: Pirelli 4 mm

Front Right Side: Pirelli 4 mm

Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	53,795.89	22,219.02	31,576.87	58.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,970.00	2,690.00	4,280.00	61.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	60,765.89	24,909.02	35,856.87	59.01
Approved Total (Overridden) (S\$)		19,500.00		
(S\$)	60,765.89	19,500.00	41,265.89	67.91
+ GST 8.00/8.00% (S\$)	4,861.27	1,560.00	3,301.27	67.91
Nett Amount (S\$)	65,627.16	21,060.00	44,567.16	67.91

INSPECTION

Date of Assignment: 04/05/2022

Date Inspected: 16/03/2022

Inspected At:

Bifrost Auto Pte Ltd
8 Kaki Bukit Avenue 4
#01-49 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 10.0 days

Adjuster: Lim Teow Guan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Feb 2023)	
Parts:	N/A	AUDI S5 3.0 CABRIOLET (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNE1648H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,632.00 FL	*1,499.00 FL
2	1		*BONNET RH HINGE	Not Damaged	231.00 FL	*- FL
3	1		*BONNET LH HINGE	Not Damaged	231.00 FL	*- FL
4	1		*BONNET LOCK	Not Damaged	189.00 FL	*- FL
5	1		*BONNET INNER HEAT INSULATOR	Not Necessary	341.00 FL	*- FL
6	1		*SET BONNET INNER HEAT INSULATOR CLIPS	Not Necessary	70.00 FL	*- FL
7	1		*FRONT BUMPER	Cut	2,778.00 FL	*1,004.00 FL
8	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FL	*30.00 FL
9	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	38.50 FL	*38.50 FL
10	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	38.50 FL	*38.50 FL
11	1		*FRONT BUMPER RH SENSOR	Short Circuit	178.00 FL	*178.00 FL
12	4		*FRONT BUMPER SENSOR HOLDER	Necessary	180.00 FL	*180.00 FL
13	1		*FRONT BUMPER LH SENSOR	Short Circuit	178.00 FL	*178.00 FL
14	1		*FRONT BUMPER RH GRILLE	Missing	231.00 FL	*215.00 FL
15	1		*FRONT BUMPER LH GRILLE	Missing	231.00 FL	*215.00 FL
16	1		*FRONT BUMPER SPOILER	Cut	1,382.00 FL	*456.00 FL
17	1		*FRONT BUMPER CENTRE SPOILER	Not Damaged	511.00 FL	*- FL
18	1		*FRONT BUMPER UNDER COVER	Not Damaged	191.00 FL	*- FL
19	1		*SET FRONT BUMPER UNDER COVER CLIPS	Necessary	70.00 FL	*30.00 FL
20	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	845.00 FL	*- FL
21	1		*FRONT BUMPER REINFORCEMENT RH BRACKET	Not Damaged	88.00 FL	*- FL
22	1		*FRONT BUMPER REINFORCEMENT LH BRACKET	Not Damaged	88.00 FL	*- FL
23	1		*FRONT BUMPER INNER SPONGE	No such part	116.00 FL	*- FL
24	1		*FRONT GRILLE WITH EMBLEM	Dented	2,084.00 FL	*1,280.00 FL
25	1		*SUPPORT PANEL TOP GARNISH	Not Damaged	115.50 FL	*- FL
26	1		*SUPPORT PANEL	Not Damaged	938.00 FL	*- FL
27	1		*AIRCON CONDENSER	Bent	1,092.00 FL	*622.00 FL
28	1		*INTERCOOLER	Dented	811.00 FL	*434.00 FL
29	1		*RH HEADLAMP ASSY	Broken	2,780.60 FL	*1,900.00 FL
30	1		*RH HEADLAMP LOWER BRACKET	Broken	73.00 FL	*73.00 FL
31	1		*RH HEADLAMP NOZZLE WASHER	No such part	251.00 FL	*- FL
32	1		*LH HEADLAMP ASSY	Broken	2,780.60 FL	*1,900.00 FL
33	1		*LH HEADLAMP LOWER BRACKET	Broken	73.00 FL	*73.00 FL
34	1		*LH HEADLAMP NOZZLE WASHER	No such part	251.00 FL	*- FL
35	1		*RH FRONT FENDER	Dented	1,129.60 FL	*925.40 FL
36	1		*RH FRONT FENDER SPLASH SHIELD (FRONT)	Torn	215.30 FL	*166.20 FL
37	1		*SET RH FRONT FENDER SPLASH SHIELD (FRONT) CLIPS	Necessary	50.00 FL	*30.00 FL
38	1		*RH FRONT FENDER SPLASH SHIELD (REAR)	No such part	215.30 FL	*- FL
39	1		*SET RH FRONT FENDER SPLASH SHIELD (REAR) CLIPS	No such part	50.00 FL	*- FL
40	1		*RH FRONT DOOR	Repair	3,884.00 FL	*- FL
41	1		*RH FRONT DOOR WEATHERSTRIP	Not Damaged	279.00 FL	*- FL
42	1		*RH FRONT SWAY BAR LINKAGE	Not Damaged	106.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*RH FRONT UPPER ARM	Bent	102.00 FL	*102.00 FL
44	1		*RH FRONT SHOCK ABSORBER	Bent	405.00 FL	*405.00 FL
45	1		*RH FRONT SHOCK ABSORBER FORK	No such part	347.00 FL	*- FL
46	1		*RH FRONT KNUCKLE ARM	Bent	702.00 FL	*585.00 FL
47	1		*RH FRONT LOWER ARM	Bent	391.00 FL	*245.00 FL
48	1		*RH FRONT TIE ROD END	Bent	97.00 FL	*97.00 FL
49	1		*RH FRONT CONTROL ARM	Bent	311.00 FL	*257.00 FL
50	1		*STEERING RACK AND PINION	Bent	4,182.00 FL	*1,995.00 FL
51	1		*RH SIDE ROCKER PANEL GARNISH	Not Damaged	1,009.00 FL	*- FL
52	1		*RH SIDE ROCKER PANEL GARNISH CENTRE SPOILER	Not Damaged	451.00 FL	*- FL
53	1		*LH FRONT FENDER	Dented	1,129.60 FL	*848.00 FL
54	1		*LH FRONT FENDER SPLASH SHIELD (FRONT)	Torn	215.30 FL	*134.00 FL
55	1		*SET LH FRONT FENDER SPLASH SHIELD (FRONT) CLIPS	Necessary	50.00 FL	*30.00 FL
56	1		*LH FRONT FENDER SPLASH SHIELD (REAR)	No such part	215.30 FL	*- FL
57	1		*SET LH FRONT FENDER SPLASH SHIELD (REAR) CLIPS	No such part	50.00 FL	*- FL
58	1		*LH FRONT DOOR	Not Damaged	3,884.00 FL	*- FL
59	1		*LH FRONT DOOR WEATHERSTRIP	Not Necessary	279.00 FL	*- FL
60	1		*LH FRONT SWAY BAR LINKAGE	Not Damaged	106.00 FL	*- FL
61	1		*LH FRONT UPPER ARM	Bent	102.00 FL	*102.00 FL
62	1		*LH FRONT SHOCK ABSORBER	Bent	405.00 FL	*405.00 FL
63	1		*LH FRONT SHOCK ABSORBER FORK	No such part	347.00 FL	*- FL
64	1		*LH FRONT KNUCKLE ARM	Bent	702.00 FL	*585.00 FL
65	1		*LH FRONT LOWER ARM	Bent	391.00 FL	*245.00 FL
66	1		*LH FRONT WHEEL BEARING	Jammed	801.00 FL	*561.00 FL
67	1		*LH FRONT TIE ROD END	Bent	97.00 FL	*97.00 FL
68	1		*LH FRONT CONTROL ARM	Bent	311.00 FL	*257.00 FL
69	1		*FRONT LH RADIATOR	Bent	734.00 FL	*655.00 FL
70	1		*LH SIDE ROCKER PANEL GARNISH	Not Damaged	1,009.00 FL	*- FL
71	1		*LH SIDE ROCKER PANEL GARNISH CENTRE SPOILER	Not Damaged	451.00 FL	*- FL
72	1		*RH FRONT WHEEL BEARING	Jammed	801.00 FL	*561.00 FL
73	1		*FRONT BUMPER LOWER SPOILER	Cut	1,550.00 FS	*629.00 FS
74	1		*BRAKE FLUID	Not Necessary	70.00 FS	*- FS
75	1		*RH FRONT SPORT RIM	Cut	1,780.00 FS	*1,000.00 FS
76	1		*RH FRONT TYRE	Cut	650.00 FS	*450.00 FS
77	1		*LH FRONT SPORT RIM	Cut	1,780.00 FS	*1,000.00 FS
78	1		*LH FRONT TYRE	Cut	650.00 FS	*450.00 FS
79	1		*RH SIDE ROCKER PANEL GARNISH LOWER SPOILER	Not Necessary	1,480.00 FS	*- FS
80	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	56,204.10	23,200.60
- List Item Discount on L Items 5.00/5.00% (\$)	2,408.21	981.58
Total Parts (\$)	53,795.89	22,219.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	3,200.00	1,000.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	2,000.00	1,000.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	100.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	120.00	0.00
5	REMOVE AND REINSTALL RADIATOR ASSY, HOSES AND FAN ASSY TO ASSIST REPAIR. TO REFILL COOLANT	New	220.00	80.00
6	REFOCUS AND ADJUST HEADLAMPS ASSY	New	60.00	30.00
7	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	New	650.00	400.00
8	ADJUST AND TEST DRIVE WHEEL ALIGNMENT SYSTEM	New	100.00	60.00
9	REMOVE AND REINSTALL RH FRONT DOOR INNER MECHANISM TO NEW DOOR	New	150.00	0.00
10	REMOVE AND REINSTALL LH FRONT DOOR INNER MECHANISM TO NEW DOOR	New	150.00	0.00
11	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIR. TO REFILL GAS	New	220.00	120.00
Gross Labour Cost (\$\$)			6,970.00	2,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >